Historic Preservation Board Staff Report



Planning Department

Author: Laura Newberry, Planning Technician

Anya Grahn, Historic Preservation Planner

Subject: Material Deconstruction and Reconstruction Review

Address: 115 Sampson Avenue

Project Number: PL-17-03580 Date: May 16, 2018

Type of Item: Administrative – Material Deconstruction and Reconstruction

Summary Recommendation:

Staff recommends the Historic Preservation Board review and discuss the application, conduct a public hearing, and approve the Disassembly/Reassembly (Panelization) and Material Deconstruction of non-historic and non-contributory materials of the Significant Historic house at 115 Sampson Avenue pursuant to the following findings of fact, conclusions of law, and conditions of approval.

Topic:

Address: 115 Sampson Avenue

Designation: Significant

Applicant: Silver Potato LLC (Joseph Sponholz and Nancy Bronstein),

represented by architect Jon Degray

Proposal: The applicant is proposing to disassemble/reassemble (panelize) the

Historic house designated as "Significant" on the City's Historic Sites Inventory. In addition, the applicant will be removing an existing non-historic parking pad along with its associated wood staircases and railroad tie retaining wall; non-historic stacked stone retaining walls and 1990s wood slat fences; post-1947 addition on the west elevation and an underground root cellar; rebuilding the historic pyramid roof and dormers; reconstructing the existing masonry chimney; raising the house 2 feet to pour a new foundation; reconstructing the historic ca.1900 wraparound porch on the east and south elevations; replacing two non-historic doors; and removing non-historic aluminum windows

and restoring 11 window openings.


Background:

The exact date of construction of this Historic house is unknown. The Summit County Recorder's Office lists the construction date as 1904 and the house first appears in a 1920s photograph of Old Town as a simple pyramid-roof cottage with a porch and no dormers. The pyramid house is one of the main three (3) house types built during the Historic Park City mining era.

The first recorded owner of the property is the Park City Townsite Corporation, and the site may have been used to house workers. It was first purchased by an individual, Frank Pintar, in 1937. He and his wife, Celia, and their son, Victor, lived in the house. Mr. Pintar and his son both worked as miners. The first mention of the property was in

the 1940 census; however, the census states that Mr. Pintar owned the house in 1935. The house was sold in 1942.

From 1907 through 1941, the Sanborn Fire Insurance Maps show that the house remained largely unchanged from the time of its construction. It was a one-and-a-half story, square pyramid-roof house with a small one story wood-frame addition off the rear (west elevation) and a wraparound porch on the south and east elevations. The first historic photo of the site is from c.1920 and shows a porch had been added to the house. No dormers were present at this time.






Photo courtesy of the Park City Museum

Since the 1941 Sanborn Fire Insurance map, there have been several additions including a rear lean-to addition along the west elevation. There is also an addition that extends off of the west elevation and is closed off from the interior of the house; this addition is constructed of railroad ties with stacked stone on the exterior. It may have been used as a root cellar at one time.

Many of the changes present on the house today are believed to have occurred between 1960 and 1980, based on their materials and designs. The window-door configuration was substantially altered after 1970, with new aluminum sliding and picture windows, flush wood doors, and trim. The windows on the east façade were modified and large, picture windows were installed. A vinyl faux-stone product was installed across the east façade and aluminum siding was used throughout. Additionally, skylights were cut into the porch roof on the south elevation. New dormers were also built after 1920, and staff believes based on their size, form, and construction that these may have been introduced in the 1970s when the house was extensively remodeled. These changes to the exterior materials and window-door configuration are significant enough to diminish the site's original character.

Additional changes were made to the site following 1982. The parking structure along Sampson Avenue, supported by packed gravel and a railroad tie retaining wall, was built in 1983 according to the Building Department's files. There is also a newer set of stairs that leads from the parking pad to the flat portion of the yard, just south of the historic house; a building permit shows these were constructed in 1995. There is also a

non-historic terraced wood patio to the south of the historic house that contains a contemporary (but vintage) hot tub.

The Historic Sites Inventory was adopted in 2009 and designated this house as Significant. It was determined to not be eligible for the National Register of Historic Places (NRHP) due to several material alterations that have changed the appearance of the historic house. Though the general form remains intact, the exterior cladding materials have been drastically altered. The window openings have been altered and the window have been replaced with aluminum frame side sliders and fixed transoms. The wrap-around shed roof porch is intact with simple square supports and decorative brackets; however, it is in poor condition and a portion of the porch roof was removed on the south elevation to install sky lights. The two gable dormers are located on opposite wall planes and have aluminum windows. The rear low-pitched gable dormer has a door rather than a window.

In February 2010, the current owner, Silver Potato LLC, purchased the property. On September 16, 2010, the Planning Department received a Historic Preservation Plan and Physical Conditions Report. On September 29, 2010, the owner met with Planning Staff for a pre-application conference. The owner was requesting to demolish the historic house. The owner was notified that a Certificate of Appropriateness for Demolition (CAD) would be required but the City recommended preserving, renovating, or reconstructing the house. They began considering redevelopment options for the site, including demolishing the historic house; however, they chose not to pursue a Certificate of Appropriateness for Demolition (CAD). On October 13, 2010, the Chief Building Official issued a Notice and Order to Repair and Vacate the historic house that required the owner to submit a HDDR application with either a Historic Preservation Plan or a plan to mothball and stabilize the historic house.

On November 4, 2011, the Planning Staff received a plan to mothball and stabilize the historic structure. The applicant stabilized the structure and mothballed it while they explored development opportunities. Work included documenting the historic house, developing a Physical Conditions Report, as-built drawings, structurally stabilizing the house, making necessary repairs to achieve the preservation plan/mothballing plan, exterminate and control pests, protect the exterior envelope from moisture penetration, secure the building and its component features to reduce vandalism and break-ins, provide adequate ventilation, secure and/or modify the mechanical utility systems, and a plan for maintenance and monitoring.

On April 10, 2013, the Building Department issued a second Notice and Order to Repair or Vacate the house. At that time, the owner, Silver Potato LLC, was still in the process of completing a HDDR Application. On March 6, 2014, Park City Council approved the 115 Sampson Avenue Subdivision through Ordinance 14-07; it was recorded on February 26, 2015. The current owners submitted a HDDR Pre-Application on April 9, 2013, to discuss opportunities to rehabilitate the historic house and construct a new addition.

The HDDR application currently under review is the most recent application. It was submitted on February 12, 2018, and the application was deemed complete February 22, 2018.

Analysis:

1. Disassembly/Reassembly (Panelization)

While the mothballing of the house in 2011 has slowed the rate of deterioration, this house is in poor condition due to the age and condition of the non-historic siding and roofing materials. The house has been uninhabited for decades, which has furthered the decline of the site and building overall. The site is also overgrown and is known for housing a family of raccoons. These animals have moved into the house by burrowing through the rotted floor structure. The Chief Building Official and Historic Preservation Planner have conducted several site visits to this site to determine the best preservation treatment. The applicant completed exploratory demolition in mid-April and provided a structural engineer's analysis that determined panelization was the best approach to preserving the historic house.

<u>15-11-14 Disassembly And Reassembly Of A Historic Building Or Historic Structure</u>

It is the intent of this section to preserve the Historic and architectural resources of Park City through limitations on the disassembly and reassembly of Historic Buildings, Structures, and Sites.

- A. CRITERIA FOR DISASSEMBLY AND REASSEMBLY OF THE HISTORIC BUILDING(S) AND/OR STRUCTURE(S) ON A LANDMARK SITE OR SIGNIFICANT SITE. In approving a Historic District or Historic Site design review Application involving disassembly and reassembly of the Historic Building(s) and/or Structure(s) on a Landmark Site or Significant Site, the Historic Preservation Board shall find the project complies with the following criteria:
 - 1. A licensed structural engineer has certified that the Historic Building(s) and/or Structure(s) cannot reasonably be moved intact; and

Complies. Structural Engineer Henry Shen has completed an analysis of the building (Exhibit E). His report outlines the structural deficiencies of the roof and floor structures. Despite the temporary shoring of the exterior walls as part of the 2011 mothballing of the house, the exterior walls have no capacity for wind, seismic, or gravity loads. He believed 75% of the exterior walls have rotted and will need to be rebuilt. He found that lifting the house in whole would be improbable due to the extent of the deterioration.

- 2. At least one of the following:
 - The proposed disassembly and reassembly will abate demolition of the Historic Building(s) and/or Structure(s) on the Site; or

- The Historic Building(s) and/or Structure(s) are found by the Chief Building Official to be hazardous or dangerous, pursuant to Section 116.1 of the International Building Code; or
- c. The Historic Preservation Board determines, with input from the Planning Director and the Chief Building Official, that unique conditions and the quality of the Historic Preservation Plan warrant the proposed disassembly and reassembly; unique conditions include but are not limited to:
 - 1. If problematic site or structural conditions preclude temporarily lifting or moving a building as a single unit; or
 - 2. If the physical conditions of the existing materials prevent temporarily lifting or moving a building and the applicant has demonstrated that panelization will result in the preservation of a greater amount of historic material; or
 - 3. All other alternatives have been shown to result in additional damage or loss of historic materials.

Complies. In 2010, the Park City Building Department issued a Notice and Order to Repair or Vacate the historic house due to its dilapidated and unsafe condition. The house was then mothballed in 2011 to temporarily shore-up the structure. Despite these efforts, the condition of the house has continued to decline. The Chief Building Official (CBO) and Planning Staff conducted site visits in April 2018, and the CBO concurs with the structural engineer's report that the deteriorated condition and structural instability of the house has prevented it from being lifted in whole. The panelization will salvage the north, south, and east walls of the historic house and ensure a greater amount of historic material than a total reconstruction.

Under all of the above criteria, the Historic Structure(s) and or Building(s) must be reassembled using the original materials that are found to be safe and/or serviceable condition in combination with new materials: and

The Building(s) and/or Structure(s) will be reassembled in their original form, location, placement, and orientation.

Complies. The applicant intends to disassemble and preserve the north, south, and east walls of the historic house; the west wall sits against the hillside leading to Sampson Avenue has largely deteriorated. Measured drawings have been submitted as part of the HDDR to document the original dimensions of the exterior walls. The applicant proposes to remove all three (3) walls in whole. To further ensure that protection of the panelized walls, staff has added the following Conditions of Approval based on the Design Guidelines:

#2. To ensure accurate reassembly, all parts of the building or element should be marked as they are systematically separated from the structure.

Contrasting colors of paint or carpenter wax crayons should be used to establish a marking code for each component. The markings should be removable or should be made on surfaces that will be hidden from view when the structure is reassembled.

#3. The process of disassembly should be recorded through photographic means; still photograph or video.

#4. As each component is disassembled, its physical condition should be noted particularly if it differs from the condition stated in the pre-disassembly documentation. If a part is too deteriorated to move, it should be carefully documented—photograph, dimensions, finish, texture, color, etc.---to facilitate accurate reproduction.

#5. Should the applicant not be able to panelize the north, south, or east wall due to its deteriorated condition following further material deconstruction, the applicant should immediately notify the Planning Department. The Planning Director, with input from the Chief Building Official and Historic Preservation Planner, may approve any deviations from this approved plan. The applicant is responsible for amending the Historic Preservation Plan and Physical Conditions Report.

1. MATERIAL DECONSTRUCTION:

This house has had significant alterations since the end of the Mature Mining Era (1894-1930). As previously described, the house was constructed without footings and rests on stone piers or directly on the dirt. The window-door configuration was modified between 1960 and 1980, leading to new aluminum sliding and picture windows that modified the original window openings. Further, the historic wood siding was covered with aluminium siding and a vinyl, faux-stone product on the east façade. Staff believes some of the dormers may have been modified at this time as well.

A. SITE DESIGN

The site is a downhill lot that extends from Sampson Avenue to the west towards Norfolk Avenue to the east. The site does not connect to Norfolk Avenue; however, the house was constructed to face town and the façade of the house is visible from Norfolk Avenue.

Currently, access to the site is from Sampson Avenue. There is a concrete parking pad that measures approximately 15 feet by 12 feet along the street. The parking pad is retained by 10 foot high railroad tie retaining walls. There are a series of wood stairs leading from the parking pad to the historic house; the architect believes that the upper stairs and landing were constructed in the 1990s and the lower stairs and landing were built before 1970. These improvements are not historic and are in dangerous condition.

The applicant is proposing to construct a new addition along the street that will feature a pedestrian entrance and single-car garage. In doing so, the applicant is proposing to remove the parking pad, railroad tie retaining wall, and series of stairs and landings that access the historic house. Staff finds that the proposed material deconstruction mitigates to the greatest extent practical any impact to the historical

importance of other structures located on the property and on adjacent parcels. These improvements are not historic and do not contribute to the historical significance of the house.

On the south side of the historic house, there is a multi-level deck containing a hot tub. The deck consists of 2 inch by 8 inch joists at 24 inches on center with 2 inch by 6 inch decking; this deck was likely introduced after the 1970s.

There are a number of retaining walls and fences on the site. Along the north property line, there is a 24-foot long wood slat fence consisting of 4 inch by 4 inch posts and 1 inch by 6 inch horizontal slats. On the south property line, there is a 30-foot long wood slat fence consisting of 6 inch by 8 inch posts and 1 inch by 6 inch vertical slats. These fences were likely built in the 1990s and are not historic. There are also stacked stone retaining walls behind the historic house in the north and south side yards. Per the photographs provided by the applicant, these improvements are in severe disrepair.

The decks, fences, and retaining walls on this property are not historic and do not contribute to the historical significance of the property. The applicant is proposing to remove these dilapidated improvements in order to redevelop the site and construct a new addition to the house. These additions to the Historic Site have been found to be non-contributory to the historic integrity and historical significance of the site.

MICES MICES

MICES

Staff has highlighted the site features proposed to be removed in red below:

B. NON-HISTORIC ADDITIONS

There is a one-story addition along the west side of the historic house that was constructed after 1947. It is seven feet wide and covered with aluminum siding. It attaches to an eight foot-wide addition that is buried in the hillside. It is walled off

from the interior of the house. The walls consist of eight inch wide railroad ties with dry stacked stone on the exterior. The walls and roof are in severe disrepair.








Addition buried in the hillside, west side of the house.

The applicant is proposing to remove these post-1947 additions. These additions to the Historic Site have been found to be non-contributory to the historic integrity and historical significance of the site.

C. ROOF

The historic house has a pyramid roof form. The east and west sides have a 12/12 pitch and the north and south sides have a 12/14 pitch. The west side of the roof transitions into a shed at an 8/12 pitch and extends into the hillside. There are simple gable dormers perpendicular to the roof on the east, west, and south sides. The roof structure consists of 1 inch by 4 inch joists at 24 inches on center, covered by 1x wood planks. The original wood shake shingle roof is covered by a standing seam metal roof that was installed after 1970. The roofing materials are in poor conditions, with the drip, fascia, and soffits requiring replacement.

In 2018, Structural Engineer Henry Shen provided an analysis of the roof structure (Exhibit E). In his report, he finds that the existing roof joists consist of 2 inch by 6 inch structural members that span 8 to 12 feet. The 8 foot joists are operating at 28% capacity and the 12 foot joists are operating at 18%. The existing roof deck is 1x wood plank installed perpendicular to the existing joists. It does not have any capacity of shear diaphragm value. The extent of repairs needed to stabilize the roof and the need to panelize the historic house make reconstructing the original pyramid roof form the best alternative.





The applicant is proposing to reconstruct the roof form. He proposes to construct dormers on all four (4) sides of the pyramid roof. Staff finds that the reconstruction of the roof and dormers on the east side of the roof are part of the restoration of the original roof form; the new dormers on the north and south sides of the roof will be incorporated into the roof form in a manner that is consistent with other historic houses. Staff is working with the applicant to ensure that the dormers are consistent in mass and scale to those that were seen historically.

D. CHIMNEY

There is an existing masonry chimney that protrudes from the top of the pyramid roof structure. The chimney is original to the structure, but has been modified over the years and no longer functions as a smoke flue. It has been significantly shortened, likely as layers of the brick deteriorated. The applicant is proposing to salvage the bricks from the historic chimney and reconstruct it on the outside of the house. Staff finds that this is necessary to restore the original chimney.



E. EXTERIOR WALLS

The exterior walls are comprised of single-wall construction with 1x12 vertical planks beneath 1 inch by 6 inch horizontal planks. They have been covered with ½ inch fiberboard and aluminum siding that was added after 1970. The structural engineer has determined that the exterior walls have no capacity for wind, seismic, or gravity loads. On the west side of the house, these walls retain the hillside, and the moisture from exposure to the ground has caused them to rot. The structural engineer found that 75% of the walls were deteriorated and would require reconstruction.

The photograph below shows the typical exterior wall construction with aluminum siding, fiber board, 1x8 horizontal lap siding and 1 inch by 10 inch vertical planks to form an interior wall.



The applicant is proposing to disassemble and preserve the north, south, and east walls of the historic house; the west wall is too deteriorated to be saved. The walls will then be reassembled over a new framed wall structure. Staff finds that the

proposed material deconstruction is necessary to restore the original house form. Because the applicant has not yet removed all of the aluminum siding and the condition of the original wood siding beneath is not yet known, staff has added the following Condition of Approval:

#7. Where the historic siding materials cannot be repaired, they shall be replaced with materials that match the original in all respects: scale, dimension, texture, profile, material, and finish. The replacement of existing historic material shall be allowed only after the applicant has demonstrated to the Planning Department that the historic materials are no longer safe and/or serviceable and cannot be repaired to a safe and/or serviceable condition. The Planning Department shall approve in writing the disposal of any historic siding materials.

F. FOUNDATION

The historic structure does not have a foundation, but there are some minimal foundation walls around the perimeter of the structure. The posts, beams, and bearing walls all sit on stacked stone, wood piles, and/or soil (see following photo). The floor joists are 2 inch x6 inch at 24 inches on center; many of the floor joists span 8 to 12 feet unsupported. The structural engineer estimates that 90% of the posts supporting the floor structure have rotted due to the amount of moisture beneath the floor structure. He recommends removing the existing foundation walls and constructing a new foundation.




The applicant is proposing to raise the historic house two feet (2') as permitted by the Design Guidelines in order to construct a new code-compliant foundation. Staff finds that the proposed work mitigates any impacts that will occur to the architectural integrity of the structure.

G. PORCH

There is an existing wraparound porch that extends across the east façade of the house and on to the south elevation. The construction of the porch roof is consistent


with that of the main roof and the roof joists do not meet code. A portion of the roofing was removed in the 1970s and new glass skylights/roofing material was added to the porch on the east elevation. The ceiling of the porch is 1x6 bead board. The porch posts and decorative ornamentation do not appear to be original. It has 1 inch by 6 inch tongue-and-groove decking above 2 inch by 4 inch joists at 24 inches on center; the decking has rotted and detached from the porch's floor structure.



The applicant is proposing to reconstruct the historic porch form and restore its historic appearance while meeting the structural requirements of the code. Staff finds that the proposed material deconstruction is necessary in order to restore the original wraparound porch.


H. DOORS

The doors have been boarded as part of the mothballing of the historic structure. There are two (2) historic door openings on the south and east elevations of the house. The existing doors are not historic and are in poor condition. The applicant is proposing to replace all the doors with new doors that are historic in appearance; these doors are highlighted in red below. Staff finds that this material deconstruction is necessary in order to restore the historic house.



I. WINDOWS

There are a total of 11 window openings on the exterior of the structure. One of the windows is completely missing; however, the other 10 openings appear to have been altered. These aluminum frame windows are not historic. The applicant is proposing to restore the original window openings and install new wood windows on the historic house; these existing window openings are highlighted in red below.




Staff finds that this material deconstruction is necessary in order to restore the historic house. To ensure that the original window openings are restored, staff has added Condition of Approval stating:

#6. Following removal of the non-historic aluminum siding, the applicant shall update his Historic Preservation Plan with a conditions report detailing the locations of original window openings. The applicant shall base any window modifications on the façade (east elevation) or secondary facades (north and south elevations) that will be visible from the Norfolk and Sampson Avenue rights-of-way on physical, measured evidence uncovered during the demolition process. Planning staff shall review and approve the updated window configuration based on this new physical evidence.

J. SHEDS

There are three (3) existing sheds on the property. These sheds were not designated as Historic on the 2009 Historic Sites Inventory. Upon closer examination, staff finds that they were likely constructed of reclaimed materials after 1960. The sheds were built on flatter portions of the lot, so that one shed is visible near the parking pad along Sampson Avenue and two are in the eastern corner of the site. Because the eastern side of the site is overgrown, staff was not able to successfully photograph these two sheds. The shed on the west side of the property is constructed of plywood.



The applicant is proposing to demolish these sheds as part of their site improvements. Staff finds that these sheds are not historic and do not contribute to the historical significance of the site.

Recommendation:

Staff recommends the Historic Preservation Board review and discuss the application, conduct a public hearing, and approve the Disassembly/Reassembly (Panelization) of the historic house as well as Material Deconstruction of non-historic and non-contributory materials at 115 Sampson Avenue pursuant to the following findings of fact,

conclusions of law, and conditions of approval. This site is listed as Significant on the City's Historic Sites Inventory (HSI).

Finding of Fact:

- 1. The property is located at 115 Sampson Avenue.
- 2. The site is designated as Significant on the Historic Sites Inventory.
- 3. On February 12, 2018, the Planning Department received a Historic District Design Review (HDDR) application for the property at 115 Sampson Avenue; it was deemed complete February 22, 2018. The HDDR application has not yet been approved as it is dependent on the HPB's Review for Material Deconstruction approval.
- 4. The exact date of construction of this house is unknown, but the Summit County Recorder's Office lists the date of construction as 1904 and it appears in 1920s photographs of Old Town as a simply pyramid-roof cottage with a porch and no dormers.
- 5. The first recorded owner of the property is the Park City Townsite Corporation, and the site may have housed mine workers. It was first purchased by an individual in 1937—Frank Pintar, his wife Celia, and son Victor lived in the house.
- 6. From 1907 to 1941, the Sanborn Fire Insurance Maps show the house remained largely unchanged. It was a one and one-half story, square pyramid-roof house with a small one-story addition on the southwest corner. It had a porch that wrapped around the east façade and south elevation.
- 7. Since the 1941 Sanborn Fire Insurance Map, there have been several additions including a rear lean-to addition across the west elevation. There is also a second addition on the west elevation that is built into the hillside and is closed off from the interior of the house. This addition is constructed of railroad ties with stacked stone on the exterior; it may have been used as a root cellar at one time.
- 8. Between 1960 and 1980, several modifications were made to the historic house that have diminished its historical significance. The window-door configuration was substantially altered after 1970, with new aluminum sliding and picture windows and flush wood doors. On the east façade, the original double-hung wood windows were replaced with large picture windows. A vinyl faux-Permastone product was installed on the east façade and aluminum siding covered the original wood drop novelty siding. Additionally, skylights were cut into the porch roof on the south elevation and new dormers were constructed after 1920.
- 9. The parking structure along Sampson Avenue was constructed in 1983 and consists of a railroad tie retaining wall with packed gravel. There is a newer set of stairs leading from the parking pad to the house, likely built in 1995.
- 10. On October 13, 2010, the Chief Building Official issued a Notice and Order to Repair and Vacate the historic house. Subsequently, the Planning Department received a plan to stabilize and mothball the house on November 4, 2011. Work included documenting the historic house, developing a Physical Conditions Report, as-built drawings, structurally stabilizing the house, making necessary repairs to achieve the preservation plan/mothballing plan, exterminate and control pests, protect the exterior envelope from moisture penetration, secure the building and its component features to reduce vandalism and break-ins, provide adequate ventilation, secure and/or modify the mechanical utility systems, and a plan for maintenance and monitoring.

- 11. On April 10, 2013, the Building Department issued a second Notice and Order to Repair or Vacate the house.
- 12. On March 6, 2014, Park City Council approved the 115 Sampson Avenue Subdivision through Ordinance 14-07; it was recorded on February 26, 2015.
- 13. Due to the deteriorated condition of the historic house and the total deterioration of the west wall against the hillside, the applicant has proposed to disassemble/ reassemble the north, south, and east walls of the historic house.
- 14. The proposal complies with LMC 15-11-14 Disassembly and Reassembly of a Historic Building or Historic Structure as:
 - a. Licensed Structural Engineer Henry Shen has certified that the Historic Building cannot be reasonably moved intact. The exterior walls have no capacity for wind, seismic, or gravity loads and 75% of the wall materials have deteriorated.
 - b. The proposed disassembly and reassembly will abate demolition of the Historic Building on the site.
 - c. The Historic Building has been found by the Chief Building Official to be hazardous or dangerous, pursuant to Section 116.1 of the International Building Code. In 2010, the Park City Building Department issued a Notice and Order to Repair or Vacate the historic house due to its dilapidated and unsafe condition. Although the house was mothballed and temporarily stabilized in 2011, the condition of the house has continued to decline.
 - d. The Historic Preservation Board determined, with input from the Planning Director and Chief Building Official, that unique conditions and the quality of the Historic Preservation Plan warrant the proposed disassembly and reassembly due to unique conditions. On April 27, 2017, the Chief Building Official concurred with the structural engineer's report dated April 26, 2018 that the deteriorated condition and structural instability of the house prevented it from being lifted in whole.
 - e. The north, south and east walls will be disassembled; the west wall has deteriorated from sitting against the hillside along Sampson Avenue. Measured drawings have been submitted as part of the HDDR application to document the original dimensions of the walls. The Building will be reassembled in their original form, location, placement, and orientation.
- 15. The applicant is proposing to demolish the non-historic c.1983 parking pad, railroad tie retaining wall, and a series of stairs and landings that access the house. The proposed material deconstruction mitigates to the greatest extent practical any impact to the historical importance of the other structures located on the property and on adjacent parcels. Further, these improvements are not historic and do not contribute to the historical significance of the house.
- 16. On the south side of the historic house, there is a 1970s multi-level deck containing a hot tub. There are also a number of stone retaining walls and 1990s wood fences along the north and south property lines. These improvements are not historic and do not contribute to the historical significance of the property. The applicant is proposing to remove these dilapidated improvements in order to redevelop the site and construct a new addition to the house. These improvements do not contribute to the historic significance or historic integrity of the site.

- 17. There are two one-story additions along the west elevation of the historic house that was constructed after 1947. The first addition is seven feet wide and covered with aluminum siding. It attaches to an 8 foot wide addition that is partially buried in the hillside. This addition consists of railroad ties and dry-stacked stone on the exterior. The walls and roof are in severe disrepair. These additions to the Historic Site have been found to be non-contributory to the historic integrity and historical significance of the site.
- 18. The historic house has a pyramid roof form. There are simple gable dormers perpendicular to the roof on the east, west, and south elevations. The roofing materials and structure are in poor condition, with the structural engineer finding that the existing roof structure does not have any capacity of shear diaphragm value. The applicant is proposing to reconstruct the roof form. Staff finds that the reconstruction is necessary for the restoration of the original roof form.
- 19. There is an existing masonry chimney that protrudes from the top of the pyramid roof structure. The chimney is original, but has been modified through shortening. The bricks and mortar are deteriorated. The applicant is proposing to salvage the bricks from the historic chimney and reconstruct it on the outside of the house. The proposed material deconstruction is necessary to restore the original chimney.
- 20. The exterior walls have no capacity for wind, seismic, or gravity loads. The west wall has rotted out, and the north, south, and east sides of the house are covered with aluminum siding. The structural engineer has found that 75% of the walls were deteriorated and would require reconstruction.
- 21. The historic structure does not have a foundation. The posts, beams, and bearing walls sit on stacked stone, wood piles, or directly on the soil. The structural engineer estimates that 90% of the posts supporting the floor structure have rotted. The applicant proposes raising the historic house 2 feet in order to construct a new foundation. The proposed material deconstruction mitigates any impacts that will occur to the architectural integrity of the structure.
- 22. There is an existing wraparound porch that extends across the east façade and south elevation of the house. A portion of the porch roof was removed in the 1970s to install new glass skylights on the east elevation. The porch posts and ornamentation are not historic and the floor structure has rotted. The applicant is proposing to reconstruct the historic porch form and restore its historic appearance. The proposed material deconstruction is necessary in order to restore the original wraparound porch.
- 23. There are only two historic door openings on the house on the south and east elevations. The existing doors are not historic and are in poor condition. The applicant is proposing to replace the doors with new wood doors that are historic in appearance. The proposed material deconstruction is necessary in order to restore the historic house.
- 24. There are a total of 11 window openings on the exterior of the structure. Ten of these openings appear to have been altered with non-historic aluminum frame windows. The applicant is proposing to restore the original window openings and install new wood windows on the historic house. The proposed material deconstruction is necessary in order to restore the historic house.
- 25. There are three existing sheds identified on the survey of the property. The sheds are not designated as historic on the 2009 Historic Sites Inventory; and these sheds

were likely constructed of reclaimed materials after 1960. The sheds were built on flatter portions of the lot. The applicant is proposing to demolish these sheds as part of their site improvements. These sheds are not historic and do not contribute to the historical significance of the site.

Conclusions of Law:

- 1. The proposal complies with the Land Management Code requirements pursuant to the HRL District and regarding historic structure deconstruction and reconstruction.
- 2. The proposal meets the criteria for disassembly and reassembly pursuant to LMC 15-11-14 Disassembly and Reassembly of a Historic Building or Historic Structure.
- 3. The proposal meets the criteria for material deconstruction pursuant to LMC 15-11-12.5 Historic Preservation Board Review for Material Deconstruction.

Conditions of Approval:

- 1. Final building plans and construction details shall reflect substantial compliance with the HDDR proposal stamped in on February 12, 2018. Any changes, modifications, or deviations from the approved design that have not been approved by the Planning and Building Departments may result in a stop work order.
- 2. To ensure accurate reassembly, all parts of the building or element should be marked as they are systematically separated from the structure. Contrasting colors of paint or carpenter wax crayons should be used to establish a marking code for each component. The markings should be removable or should be made on surfaces that will be hidden from view when the structure is reassembled.
- 3. The process of disassembly should be recorded through photographic means; still photograph or video.
- 4. As each component is disassembled, its physical condition should be noted particularly if it differs from the condition stated in the pre-disassembly documentation. If a part is too deteriorated to move, it should be carefully documented—photograph, dimensions, finish, texture, color, etc.---to facilitate accurate reproduction.
- 5. Should the applicant not be able to panelize the north, south, or east wall due to its deteriorated condition following further material deconstruction, the applicant should immediately notify the Planning Department. The Planning Director, with input from the Chief Building Official and Historic Preservation Planner, may approve any deviations from this approved plan. The applicant is responsible for amending the Historic Preservation Plan and Physical Conditions Report.
- 6. Following removal of the non-historic aluminum siding, the applicant shall update his Historic Preservation Plan with a conditions report detailing the locations of original window openings. The applicant shall base any window modifications on the façade (east elevation) or secondary facades (north and south elevations) that will be visible from the Norfolk and Sampson Avenue rights-of-way on physical, measured evidence uncovered during the demolition process. Planning staff shall review and approve the updated window configuration based on this new physical evidence.
- 7. Where the historic siding materials cannot be repaired, they shall be replaced with materials that match the original in all respects: scale, dimension, texture, profile, material, and finish. The replacement of existing historic material shall be allowed only after the applicant has demonstrated to the Planning Department that the

historic materials are no longer safe and/or serviceable and cannot be repaired to a safe and/or serviceable condition. The Planning Department shall approve in writing the disposal of any historic siding materials.

Exhibits:

Exhibit A – HPB Checklist for Material Deconstruction

Exhibit B – <u>Historic Sites Inventory Form</u>

Exhibit C – Plans

Exhibit D – Physical Conditions Report + Historic Preservation Plan

Exhibit E – Structural Engineer's Report

Exhibit F - CBO Determination Letter, 4.26.18


Historic Preservation Board Material Deconstruction Review Checklist:

- Routine Maintenance (including repair or replacement where there is no change in the design, materials, or general appearance of the elements of the structure or grounds) does not require Historic Preservation Board Review (HPBR).
- 2. The material deconstruction is required for the renovation, restoration, or rehabilitation of the building, structure, or object.
- Proposed exterior changes shall not damage or destroy the exterior architectural features of the subject property which are compatible with the character of the historic site and are not included in the proposed scope of work.
- 4. The proposed scope of work mitigates any impacts that will occur to the visual character of the neighborhood where material deconstruction is proposed to occur; any impacts that will occur to the historical significance of the buildings, structures, or objects located on the property; any impact that will occur to the architectural integrity of the buildings, structures, or objects located on the property; and any impact that will compromise the structural stability of the historic building.
- 5. The proposed scope of work mitigates to the greatest extent practical any impact to the historical importance of other structures located on the property and on adjacent parcels.
- 6. Any addition to a Historic Building, Site, or Structure has been found to be non-contributory to the historic integrity or historical significance of the structure or site.

115 SAMPSON AVENUE RESIDENCE HISTORIC DISTRICT DESIGN REVIEW SET

115 SAMPSON AVENUE, PARK CITY, UTAH 84060

CONSULTANTS




SURVEYOR'S CERTIFICATE



NOTES

- 2. The architect is responsible for verifying building setbacks, zoning requirements and building heights.
- This tupographic map is based on a field survey performed on July 24, 1998 and updated on July 25, 2006 and November 16, 2007.
- 4. See recorded survey 5-6749.

LINE	BEARING	DISTANCE		
Li	S 80'02'00" E	11.00		
1.2	N 13'33'20" E	17.29		







STAFF: MARSHALL KING BLAKE MYERS CHIP TOMSUDEN


115 SAMPSON AVENUE BLOCK 78, PARK CITY SURVEY


EXISTING CONDITIONS


FOR: GERMAINE PARTNERS
JOB NO.: 3-1-08
FILE: X:\ParkChySurvey\dwg\arv\tegc2008\030108.dwg


SHEET


OF
































WINDOW SCHEDULE										
MARK	SIZE WIDTH HEIGHT		TYPE	FRAME MAT'L	EXTERIOR FINISH	INTERIOR FINISH	GLAZING	REMARKS		
0										
A	7-0*	5-0"	DOUBLE HUNG	WOOD ALLYM, CLAD	MANUFACTURE	STAIN & VARNISH	PSULATED - LOW E			
В	9-0*	5-0"	DOUBLE HUNG	WOOD ALLIN, CLAD	MANUFACTURE	STAIN & VARNISH	INSULATED - LOW E	(2) 7 5'x 5' 0' DOUBLE HUNG MULLED - SEE ELEVATION		
_ C	2-6"	5-0"	CASEMENT	WOOD ALLIN, CLAD	MANUFACTURE	STAIN & VARNISH	INSULATED - LOW E			
D D	9-0*	6-6"	CASEMENT/TRANSON	WOOD ALUM, CLAD	MANUFACTURE	STAIN & VARNISH	INSULATED - LOW E	(2) 7 6"x 5" 0" CASEMENT MULLED TO (2) 2" 6"x 1" 0" TRANSOM - SEE ELEVATION		
E	2-6"	1-6"	AWNING	WOOD ALLIN, CLAD	MANUFACTURE	STAIN & VARNISH	INSULATED - LOW E			
F	3-0"	6-6"	CASEMENTITRANSON	WOOD ALLIN, CLAD	MANUFACTURE	STAIN & VARNISH	INSULATED - LOW E	3" 0" x 5" 0" CASEMENT MULLED TO 3" 0" x 1" 0" TRANSON - SEE ELEVATION		
G	2-0*	4-0"	DOUBLE HUNG	WOOD ALLIN, CLAD	MANUFACTURE	STAIN & VARNISH	INSULATED - LOW E			
Н	440	4-0"	DOUBLE HUNG	WOOD ALLIN, CLAD	MANUFACTURE	STAIN & VARNISH	INSULATED - LOW E	(2) 7-4"s 4-4" DOUBLE HUNG MULLED - SEE ELEVATION		
- 1	8-0"	6-6"	CASEMENTITRANSON	WOOD ALLIN, CLAD	MANUFACTURE	STAIN & VARNISH	INSULATED - LOW E	(3) 7 F's 5 F' CASEMENT MULLED TO (3) 7 F's 1 F' TRANSOM - SEE ELEVATION		
K	9-0"	3-6"	CASEMENT	WOOD ALLIN, CLAD	MANUFACTURE	STAIN & VARNISH	INSULATED - LOW E	(T) 7-6"x 7-6" CASEMENT MULLED - SEE ELEVATION		
	7-6*	4-8"	CASEMENT	WOOD ALLIN, CLAD	MAXUEACTURE.	STAIN & VARNISH	INSULATED - LOW E			
N	2-6*	8-6"	CASEMENT/TRANSON	WOOD ALLIN, CLAD	MAXUEACTURE	STAIN & VARNISH	INSULATED - LOW E	2 6'x 5 0' CASEMENT MULLED TO 2 6'x 1 0' TRANSON - SEE ELEVATION		
N	5-0"	9-0"	AWN/CASE/TRANSOM	WOOD ALLIN, CLAD	MAXUEACTURE	STAIN & VARNISH	INSULATED - LOW E	CLOSE'S Z SC AWNING TO CLOZE S'S S' CASEMENT TO CLOZE S'S LOS' TRANS, MULLED - SEE ELEV.		
P	7-6*	7-6*	AWNINGCASEMENT	WOOD ALLIN, CLAD	MAXUEACTURE	STAIN & VARNISH	INSTITUTED-100/F	2 6'x 2' 6' AWNING MULLED TO 2 6'Y 5' 0' CASEMENT - SEE ELEV.		
					MUNITED	DIVERTE CONTRACTOR				
-										
-		_								
\vdash										
	_	-	_							

WINDOW I	NOTES
----------	-------

I. ALL WINDOWS OPENINGS TO BE FIELD VERIFIED BY CONTRACTOR BEFORE INSTALLATION.

3. ALL WINDOWS IN BATHROOMS MUST BE TEMPERED GLASS

5. EGRESS WINDOWS: FINISH SILL HT. MIN 44" FROM FLOOR MIN. CLEAR OPENING OF 5.7 S/F MIN NET CLEAR OPENING 20" WIDTH AND 24" HT.

6. ALL WINDOWS TO HAVE A MIN. U-VALUE OF .31

				SCI			ΜF		FLC		
REMARKS	ì	JNG	CEII		LLS	WA	ROOM				
REWARKS	IATL	MATL	HEIGHT	WEST	SOUTH	EAST	NORTH	BASE	MAT'L	NAME	NO.
	•		EVEL	MAIN L	HISTORIC	R LEVEL	LOWE				
	GVP	GYP	VARIES	GYP	GNP	GYP	GYP		CONCRETE	ELEVATOR	100
	GYP	GJ5	84139"	GYP	GAP.	GYP	GYP	W000	CARPET	MST BEDROOM	991
	GYP	635	8'41 34"	GYP	635	GYP	GYP	W000	CARPET	CLOSET	102
	GYP	635	8'41 34"	GYP	635	GYP	GYP	TILE	TILE	MST BATH	103
	GJ5.	GJ5	VARIES	GYP	675	GYP	GYP	W000	GOOW	HALL	394
	GJ5.	GJ5	VARIES	GYP	675	GYP	GYP	W000	GOOW	FAMILY ROOM	105
	GJ5.	GJ5	VARIES	GYP	675	GYP	GYP	W000	GOOW	WETBAR	396
	GJ5.	GJ5	H-1134"	GYP	675	GYP	GYP	W000	GOOW	HALL	107
	GJ5.	GJ5	84134"	GYP	675	GYP	GYP	TILE	TILE	BATH	108
	GJ5.	GJ5	VARIES	GYP	675	GYP	GYP		GRAVEL	MECHANICAL	399
	GNP		84139"	GYP	635	GYP	GYP	TILE	TILE	LAUNDRY	110
	GNP		84138	GYP	GJP	GYP	GYP	TILE	TILE	BATH	111
	GJ5.	GJ5	84134"	GYP	675	GYP	GYP	W000	CARPET	BEDROOM	112
	GJ5.	GJ5	84134"	GYP	675	GYP	GYP	W000	CARPET	CLOSET .	113
	GNP		84139"	GYP	635	GYP	GYP	TILE	TILE	BATH	114
	GJ5.	GJ5	VARIES	GYP	675	GYP	GYP	W000	CARPET	BEDROOM	115
				EL	OND LEV	SEC					
	GIP	GYP	VARIES	GYP	G)P	GYP	GYP	W000	CARPET	BEDROOM	301
	635	635	VARIES	GTP	635	GYP	GYP	TILE	TILE	BATH	302
	635	635	VARIES	GYP	635	GYP	GYP	W000	GOOW	DENING ROOM	203
	635	635	VARIES	GYP	635	GYP	GYP	W000	GOOW	LIVING ROOM	394
	635	635	VARIES	GYP	635	GYP	GYP	W000	GOOW	KITCHEN	305
	635	635	VARIES	GYP	635	GYP	GYP	TILE	TILE	POWDER	306
	635	635	VARIES	GYP	635	GYP	GYP	W000	GOOW	PANTRY	307
											308
											309
											210
											211
											212
	•			EL.	IRD LEVE	TH					
"X" GYPSUM BOARD	GYP 58" TY	GYP	VARIES	GYP	GYP	GYP	GYP	W000	CONCRETE	GARAGE	301
	GYP		VARIES	GYP	GYP	GYP	GYP	TILE	TILE	ENTRY	302
		- "		-11							
						_					

	DOOR SCHEDULE											
MARK	TYPE		SIZE		DOOR	DOOR	FRAME	FRAME	HDWR	REMARKS		
0	TIPE	WIDTH	HEIGHT	THICK.	MAT'L	FINISH	MAT'L	FINISH	TYPE	REMARKS		
	LOWER LEVEL/HISTORIC MAIN LEVEL											
101	STYLE & RAIL	24"	68*	139"	W000	STAIN & VARNISH	W000	STAIN & VARNISH	PRIVACY			
102	STYLE & RAIL	24"	6-8"	134"	W000	STAIN & VARNISH	W000	STAIN & VARNISH	PRIVACY			
163	SHOWER	2-2"	628*	1.2"	GLASS	CLEAR	GLASS		SHOWER	TEMP - FURO GLASS ENCLOSURE		
164	STYLE & RAIL	24"	6-8"	139"	W000	STAIN & VARNISH	4000	STAIN & VARNISH	PASSAGE			
105	STYLE & RAIL	2-8° 2-8°	68	139"	WOODGLASS	STAIN & VARNISH	W000	STAIN & VARNISH	FRED	INSUL-LOW E-TEMP-WEATHER STRIP		
105	STYLE & RAIL STYLE & RAIL	2-8	6.8"	134"	WOOD GLASS	STAIN & VARNISH STAIN & VARNISH	W000	STAIN & VARNISH STAIN & VARNISH	10CKSET PRIVACY	INSUL-LOW E-TEMP-WEATHER STRIP-THRESHOLD		
108	FRENCH W/ TRANSOM	24	8776	139"	WOOD-ALUM	STAIN & VARNISH	WOOD-ALUM	STAIN & VARNISH	10CKSET	INSUL-LOW E-TEMP-WEATHER STRIP-THRESHOLD-SEE FLEV.		
109	STYLE & RAIL	24	8.07	139"	MOOD-ATCH	STAIN & VARNISH	WOOD	STAIN & VARNISH	PRIVACY	INSUL-LOW E-12MP- 9EATHER STRIP - THRESHOLD - SEE FLEV.		
110	FRENCH W/ TRANSOM	8-6	8 T/T G	139	WOOD-ALUM	STAIN & VARNISH	WITH GOOD		10CKSET	INSUL-LOW E-TEMP-WEATHER STRIP-THRESHOLD-SEE FLEV.		
111	FRENCH W/ TRANSOM	8.6	84716	139"	WOOD-ALUM		WOOD-ALUM		FINED	INSUL LOW E-TEMP-WEATHER STRP-SEE ELEV.		
112	FRENCH W/ TRANSOM	24"	847.16	139"	WOOD-ALUM	STAIN & VARNISH	WOOD-ALUM	STAIN & VARNISH	10CKSET	INSUL LOW E-TEMP-WEATHER STRP-THRESHOLD-SEE ELEV.		
113	SHOWER	2-2"	7.0"	1.2"	GLASS	CLEAR	GLASS		SHOWER	TEMP-HURO GLASS ENCLOSURE		
114	STYLE & RAIL	2-4"	8'0"	139"	WOOD	STAIN & VARNISH	W000	STAIN & VARNISH	PRIVACY			
115	STYLE & RAIL	347	8'0"	134"	W000	STAIN & VARNISH	W000	STAIN & VARNISH	PASSAGE	ELEVATOR - WEATHER STRIP - THRESHOLD		
116	STYLE & RAIL	24"	8'0"	134"	W000	STAIN & VARNISH	W000	STAIN & VARNISH	PASSAGE			
117	STYLE & RAIL	24"	8'0"	134"	W000	STAIN & VARNISH	W000	STAIN & VARNISH	PASSAGE			
138	STYLE & RAIL	24"	8:0"	134"	W000	STAIN & VARNISH	W000	STAIN & VARNISH	PRIVACY			
119	STYLE & RAIL	24"	8'0"	134"	W000	STAIN & VARNISH	#000	STAIN & VARNISH	PRIVACY			
120	STYLE & RAIL	24"	8:0"	139"	W000	STAIN & VARNISH	#00D	STAIN & VARNISH	PASSAGE			
121	STYLE & RAIL	24"	8'-0"	139"	W000	STAIN & VARNISH	W000	STAIN & VARNISH	PRIVACY			
122	SHOWER	2-2"	7'0"	1.2"	GLASS	CLEAR	GLASS		SHOWER	TEMP - EURO GLASS ENCLOSURE		
_					_				_			
					_							
MAIN LEVEL/HISTORIC UPPER LEVEL												
2H	SHOWER	2-2"	628*	1.2"	GLASS	CLEAR	GLASS		SHOWER	TEMP - FURO GLASS ENCLOSURE		
292	STYLE & RAIL	24"	6-8"	139"	W000	STAIN & VARNISH	W000	STAIN & VARNISH	PRIVACY			
263	FRENCH W/ TRANSOM	5-6*	847/1-61	130"	WOOD-ALUM			STAIN & VARNISH	FRED	INSUL-LOW E-TEMP-WEATHER STRP-SEE ELEV.		
284	FRENCH W/ TRANSOM STYLE & RAIL	5-6°	8 T/T G 8 T	134"	WOOD-ALLM	STAIN & VARNISH STAIN & VARNISH	WOOD-ALUM WOOD	STAIN & VARNISH STAIN & VARNISH	1.OCKSET PASSAGE	INSUL-LOW E-TEMP-WEATHER STRIP-THRESHOLD-SEE FLEV. ELEVATOR-WEATHER STRIP-THRESHOLD		
286	STYLE & RAIL	24"	8.0	139"	WOOD	STAIN & VARNISH	W000	STAIN & VARNISH	PRIVACY	POCKET DOOR		
297	STYLE & RAIL	24	8.0	139"	WOOD	STAIN & VARNISH	W000	STAIN & VARNISH	PASSAGE	TOCALITIONS.		
288	FRENCH	74"	820	130"	WOOD-ALUM	STAIN & VARNISH	WOOD-ALUM	STAIN & VARNISH	LOCKSET	INSUL - LOW E - TEMP - WEATHER STRIP - THRESHOLD - SEE FLEV.		
	UPPER LEVEL											
381	OVER HEAD DOOR	8-8	8.0"	134"	WOODGLASS	STAIN & VARNISH	W000	STAIN & VARNISH	GARAGE	DISUL - LOW E - TEMP - AUTO DOOR OPENER		
342	STYLE & RAIL	240*	8:0"	139"	W000	STAIN & VARNISH	W000	STAIN & VARNISH	10CKSET	20 MIN - SELF LATCHING - SMOKE SEAL - THRESHOLD		
363	STYLE & RAIL	3-4"	8'0"	139"	WOODGLASS		W000	STAIN & VARNISH	10CKSET	INSUL - LOW E - TEMP - WEATHER STRIP - THRESHOLD		
364	STYLE & RAIL	3-17	8'0"	139"	WOOD	STAIN & VARNISH	W000	STAIN & VARNISH	PASSAGE	ELEVATOR - WEATHER STRIP - THRESHOLD		

DOOR NOTES

2. ALL DOORS TO BE 1 3/4" SOLID CORE UNLESS NOTED OTHERWISE.

3. ALL SHOWER DOORS AND GLASS SHOWER ENCLOSURES SHALL BE TEMPERED GLASS. IRC SECTION R308.3 AND R308.4

1. ALL DOOR OPENINGS TO BE FIELD VERIFIED BY CONTRACTOR BEFORE INSTALLATION.

4. FRENCH/PATIO/TERRACE/NANNA DOORS TO BE SUPPLIED BY WINDOW MANUFACTURE TO HAVE A U-VALUE OF .31 MINIMUM.

5. AUTOMATIC GARAGE DOOR OPENERS SHALL BE TESTED IN ACCORDANCE WITH UL325. - IRC 309.4.

SCHEDULES
DOOR, WINDOW AND ROOM

DeGray

Jonathan De
A r c h i t 6
P.O. BOX 1674, 614 Main Street, Sales 202. Pa
Tel. 435, 646-7263, E-mail. de grayench@y

115 SAMPSON AVENUE, PARK CITY, UTAH 84060 115 SAMPSON AVENUE RESIDENCE HISTORIC DISTRICT DESIGN REVIEW SET

FEBRUARY 02, 2018

A6.1



PHYSICAL CONDITIONS REPORT

	For Use with the Historic District Design Review (HDDR) Application						
	For Official Use Only						
PLANNER:	APPLICATION #:						
	DATE RECEIVED:						
PROJECT INFORMA	TION						
NAME:	Joseph Sponholz and Nancy Bronstein						
ADDRESS:	115 Sampson Avenue						
	Park City, Utah						
TAX ID:	PC-718-1OR						
SUBDIVISION:	OR						
SURVEY:	LOT #:BLOCK #:						
HISTORIC DESIGNAT	TION: LANDMARK X SIGNIFICANT NOT HISTORIC						
APPLICANT INFORM	MATION						
NAME:	Joseph Sponholz and Nancy Bronstein						
MAILING	25 East End Avenue						
ADDRESS:	New York, NY 10028-7052						
DUONE #							
PHONE #:	() - FAX #: () -						
EMAIL:	nebronstein@gmail.com; jgsponholz@gmail.com						
APPLICANT'S REPRI	ESENTATIVE INFORMATION						
NAME:	Jonathan DeGray						
PHONE #:	435-649-7263						
EMAIL:	degrayarch@qwestoffice.net						

ACKNOWLEDGMENT OF RESPONSIBILITY

This is to certify that I am making an application for the described action by the City and that I am responsible for complying with all City requirements with regard to this request. This application should be processed in my name and I am a party whom the City should contact regarding any matter pertaining to this application.

I have read and understood the instructions supplied by Park City for processing this application. The documents and/or information I have submitted are true and correct to the best of my knowledge. I understand that my application is not deemed complete until a Project Planner has reviewed the application and has notified me that it has been deemed complete.

I will keep myself informed of the deadlines for submission of material and the progress of this application. I understand that a staff report will be made available for my review three days prior to any public hearings or public meetings. This report will be on file and available at the Planning Department in the Marsac Building.

I further understand that additional fees may be charged for the City's review of the proposal. Any additional analysis required would be processed through the City's consultants with an estimate of time/expense provided prior to an authorization with the study.

Signature of Applicant:	Name of Applicant: Joseph Sponholz				
	25 East End Avenue, New York, NY 10028- 7052				
Address:					
Phone #:	() - Fax #: () -				
Email:	gsponholz@gmail.com				
Type of Application:					
AFFIRMATION OF SUFFICIE	NT INTEREST				
•	title owner of the below described property or that I have written authorization from the owner to or the affirm that I am aware of the City policy that no application will be accepted nor work				
Performed for properties that ar	re tax delinquent.				
Name of Owner:	Joseph Sponholz				
Mailing Address: 25 East End Avenue, New York, NY 10028 - 7052					
	115 Sampson Ave., 115 Sampson e-plat				
Street Address egal Description of Su ect Prop	perty				
Signature:	Date: 2-5-18				

- 1. f you are not the fee owner attach a copy of your authorization to pursue this action provided y the fee owner.
- 2. f a corporation is fee titleholder, attach copy of the resolution of the Board of Directors authorizing the action.
- 3. f a oint venture or partnership is the fee owner, attach a copy of agreement authorizing this action on ehalf of the oint venture or partnership
- 4. If a Home Owner's Association is the applicant than the representative/president must attaché a notarized letter stating they have notified the owners of the proposed application. A vote should e taken prior to the su mittal and a statement of the outcome provided to the City along with the statement that the vote meets the requirements set forth in the CC s.

Please note that this affirmation is not submitted in lieu of sufficient title evidence. You will be required to submit a title opinion, certificate of title, or title insurance policy showing your interest in the property prior to Final Action

P YS CA C ND NS EP

Detailed Description of Existing Conditions. Use this page to describe all existing conditions. Number items consecutively to describe all conditions, including building exterior, additions, site work, landscaping, and new construction. Provide supplemental pages of descriptions as necessary for those items not specifically outlined below.

1. Site Design

This section should address landscape features such as stone retaining walls, hillside steps, and fencing. Existing landscaping and site grading as well as parking should also be documented. Use as many boxes as necessary to describe the features of the site. Supplemental pages should be used to describe additional elements and features.

Element	eature <u>opography</u>							
his involves	☐ An original part☐ A later addition	of the uilding	Estimate	ed date of c	onstruction			
Descri e e isting f	eature							
is a parking pad of elevation at the p railroad tie retain of a out 60 feet he elevation 7268 fe appro imately 28 is appro imately	pes downhill from weston the uphill side off control of the property noriz. Hen slopes appet this flat area is what feet vert. At a distance elevation 7240 feet.	of Sampson Ave Avenue is appropriate slopes downhile for or imately 6 fector imately 6 fect	enue. he ro imately II from Salet vert. at structure eet horiz.	parking pac 7300 feet. mpson Aver a distance sits. he si o the end rical sheds o	t is a out 15 he pad is s nue appro in of a out 40 te continues of the prope	feet wide a chored up y mately 32 fe feet horiz. downhill to rty. he eas	nd 12 feet de a 10 foot hig et vert. at a d o appro ima the east t end of the p	eep. he gh listance tely property
E isting Condition	E cellent □	Good □	air 🗆	Poor 🗆				
Photo Num ers		Ilustration Nu	m ers 1	of 1, AB.1, A	40.1, A0.1			

f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

Element eature <u>andscaping, Steps, Deck, etaining wall, ence</u>
his involves — An original part of the uilding

A later addition — Estimated date of construction After 1970

Descri e e isting feature

All of the vegetation is natural and over grown. here are two large cottonwoods on the south side of the house and one on the east side. here are a series of wooden stairs and landings from the parking pad to the house. he wooden stairs landings from the upper pad to the deck were uilt after 1990 and need repair. he lower stairs landings are in disrepair and were uilt after 1970. here are a series of stone steps leading to the deck. he stone steps were uilt efore 1970. he deck on the south side of the house is 2 8 oists at 24 inches o.c. with 2 6 decking uilt after 1970. he deck is in disrepair. 10 foot high rail road tie retaining wall on the uphill side of the property which shores up a parking pad off of Sampson Avenue. he pad is appro imately 15 feet wide and 12 feet deep. he elevation at the parking pad Sampson Avenue is appro imately 7300 feet. he retaining wall was uilt after 1970 and is in disrepair. South property line fence is approximately 30' long and is built of 6x8 post 1x6 slats vertical. North property line fence is approximately 24 feet long and is uilt of 4 4 posts with 1 6 slats horizontal. Built after 1990

E isting Condition	E cellent □	Good □	air 🗆	Poor
Photo Num ers 1a, 1	, 1c, 1d, 1e, 1f,	1g, 1h, 1		Ilustration Num ers 1 of 1, A0.1, A0.2

Photo 1a: Downhill site looking east



f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

Photo 1b: Stairs from stone steps to deck



Photo 1c: Stone steps



Photo 1d: Deck south side of house



Photo 1e: Retaining wall looking north




Photo 1f: Retaining wall looking west




Photo 1g: Fence at south property line



Photo 1h: Fence at south property line



Photo 1j: Fence at north property line



f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

144

2. Structure

Use this section to describe the general structural system of the building including floor and ceiling systems as well as the roof structure. Supplemental pages should be used to describe additional elements and features.

Element eature <u>istoric orm and Stucture</u>

his involves

- An original part of the uilding
- A later addition


Estimated date of construction 1900

Descri e e isting feature

he e isting structure at 115 Sampson Avenue was uilt a out 1900. he house is a 1 1 2 story pyramid form. he low shed roof covers the porch that wraps around the south and east elevations. The 7' addition off the west was built after 1947. he istoric structure has no foundation and all posts, eams and earing walls sit on stacked stone and soil. The floor joist are 2x6 @ 24" o.c. The floor sheathing is 1x6 plank. The walls are 8" horizontal wood lap siding on 1x10 vertical plank. The upper floor joist are 2x8 @ 24" o.c. The floor sheathing is 1x6 plank. The roof is wood shake shingles on 1x plank on 2x4 joist @ 24" o.c. with 1x6 collar ties @ 48" o.c. The low shed roof is wood shake shingles on 1x plank on 2x4 joist @ 24" o.c. The wrap around porch is 1 6 decking on 2x4 joist @ 24" o.c. with 2x8 support eams. he addition uilt after 1947 is the same construction. he root cellar is an 8 foot wide structure perpendicular to the west addition and dies into the hillside. he inside of the house has een walled off to this space. he walls are 8 inch rail road ties with dry stack stone on the e terior side. he walls and roof are in disrepair. See Structural Engineers report.

E isting Condition	E cellent	Good \square	air 🗀	Poor	
Photo Num ers 2a, 2	, 2c	llus	tration Num	ı ers	AB.1

Photo 2a: Typical floor assembly 1x6 plank on 2x6 joist bearing on stone/soil




f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

Photo 2b: Typical exterior wall, aluminum siding on 1/2" fiber board in 1x8 horiz. lap on 1x10 vert. plank



Photo 2c: Typical joist bearing on stone/soil



3. Roof

Use this section to describe the roofing system, flashing, drainage such as downspouts and gutters, skylights, chimneys, and other rooftop features. Supplemental pages should be used to describe additional elements and features.

Element eature oof Assem ly

his involves An original part of the uilding

■ A later addition Estimated date of construction 1900-1970

Descri e e isting feature

he roof is a simple hip. he east and west have a 12 12 pitch and the north and south have 12 14 pitch. he west side of the roof continues to shed down at an 8 12 pitch. he west side of the roof has a simple galle perpendicular that dies into the hill side. here are dormers on the east, west and south. he roof is standing seam metal roof over wood shake shingles over 1 wood plank over 2 4 oist at 24 inches o.c. he oists, 1 planks and wood shakes seem to e original. he standing seam metal roof was installed after 1970. he wrap around porch roof is a simple shed hip with a 7 12 pitch. he construction of the porch roof is the same as the main roof. All drip metal, fascia and soffit needs to e replaced repair.

Photo Num ers 3a, 3, 3c, 3d, 3e, 3f Illustration Num ers AB.1

Photo 3a: West elevation




Photo 3b: North and East elevations



Photo 3c: South elevation



f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

Photo3d: West and south elevation looking down at the root cellar roof/wall



Photo 3e: West dormer



f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

Photo 3f: South dormer



f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

4. Chimney

Use this section to describe any existing chimneys. One box should be devoted to each existing chimney. Supplemental pages should be used to describe additional elements and features.

Element eature _	asonry chimney				
his involves	An original part	t of the uilding	g		
	□ A later addition		Estima	ated date of construction 1900	
Descri e e isting fe	eature				
1	mney is original to the has been modified			e chimney no longer functions as a smoke flue. The ds repair.	ne
E isting Condition	E cellent □	Good \square	air 🗆	Poor	
Photo Num ers 4a	a, llustra	ation Num ers	AB.1		

Photo 4a: Masonry chimney



5. Exterior Walls

Use this section to describe exterior wall construction, finishes, and masonry. Be sure to also document other exterior elements such as porches and porticoes separately. Must include descriptions of decorative elements such as corner boards, fascia board, and trim. Supplemental pages should be used to describe additional elements and features.

Element eature <u>E terior wall assem ly</u>					
his involves An original part of the uilding					
☐ A later addition Estimated date of construction 1900					
Describes follows					
Descri e e isting feature					
E terior wall assem ly Aluminum siding on ½" fiber board (after 1970) on 1 8 horizontal lap siding on 1 10 vertical plank historical .					
E isting Condition					
Photo Num ers 2 , 3 , 3c, 3e, 3f Illustration Num ers AB.1					
6. Foundation Use this section to describe the foundation including its system, materials, perimeter foundation drainage, and other foundation-related features. Supplemental pages should be used to describe additional elements and features.					
Element eature <u>oundation</u> his involves An original part of the uilding					
☐ A later addition Estimated date of construction					
Descri e e isting feature					
he e isting structure has no foundation and all posts, eams and earing walls sit on stacked stone and soil. See 2. Structure and Structural Engineers report.					
E isting Condition					
Photo Num ers 2a, 2c Illustration Num ers AB.1					

f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

7. Porches

Use this section to describe the porches Address decorative features including porch posts, brackets, railing, and floor and ceiling materials. Supplemental pages should be used to describe additional elements and features.

Element eature Porch

his involves

An original part of the uilding

☐ A later addition

Estimated date of construction 1900-1907

Descri e e isting feature

he porch was added etween 1900 and 1907. he porch wraps around the east and south elevations. he deck is G decking on 2 4 oists @ 24" o.c. with 2 8 support eams. he oists sit on stack stone soil. he deck sags 3 inches in 4 feet. he posts are 4 4 with decorative rackets. he roof porch on the south elevations has een partially enclosed with glass. he glass was added in parts of the roof after 1970. he soffit is 1 6 ead oard.

E isting Condition

E cellent □ Good □

air 🗆

Poor -

Photo Num ers 7a, 7 , 7c, 7d, 7e

Ilustration Num ers AB.1

Photo 7a: Porch south elevation



f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

Photo7b: Porch south elevation



Photo 7c: Porch east elevation




f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

Photo 7d: Porch soffit



Photo 7e: Porch decorative brackets



f you have questions regarding the requirements on this application or process please contact a mem er of the Park City Planning Staff at 435 615-5060 or visit us online at www.parkcity.org. Updated 10 2014.

8. Mechanical System, Utility Systems, Service Equipment & Electrical

Use this section to describe items such as the existing HVAC system, ventilation, plumbing, electrical, and fire suppression systems. Supplemental pages should be used to describe additional elements and features.

Element/Feature:	Mechanical,	Electrical	and	Plumbing

This involves:

An original part of the building

■ A later addition Estimated date of construction: After 1947

Describe existing feature:

Forced air furnace is not up to code. The furnace distribution is through a single vent opening at the stairs. The water heater is located in the bathroom closet. The water heater is not insulated, seismically anchored or installed to code. All the plumbing and electrical is in bad shape and not up to code. The existing stove in the living room connects to the masonry chimney. There is an electric base heater in the west bedroom.

Existing Condition: Excellent Good Fair Poor

Photo Numbers: 8a, 8b, 8c, 8d, 8e, 8f, 8g, 8h, 8j Illustration Numbers: AB.1

Photo 8a: Furnace



Photo 8b: Water Heater



Photo 8c: Electrical breaker box in bathroom closet



If you have uestions regarding the re-uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

Photo 8d: Electrical breaker box in bathroom closet





Photo 8e: Mechanical/Electrical/Plumbing in bathroom closet




If you have uestions regarding the re-uirements on this application or process please contact a member of the Par-City Planning taff at 4 1 or visit us online at www.par-city.org. pdated 1 / 14.

Photo 8f: Main level bathroom



Photo 8g: Upper level toilet and sink



If you have uestions regarding the re-uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

Photo 8h: Stove in living room



Photo 8j: Stove pipe to masonry chimney



If you have uestions regarding the re-uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

9. Door Survey

Total number of door openings on the exterior of the structure:

Number of historic doors on the structure:

Number of existing replacement/non historic doors:

Number of doors completely missing: 4

Number of doors to be replaced:

Door #:	Existing Condition (Excellent, Good, Fair, Poor):	Describe any deficiencies:	Photo #:	Historic (50 years or older):
D1	Poor		9a	
D2	Poor		9b	
D3	Poor			
D4	Poor			
D5	Poor			

10. Window Survey

Total number of window openings on the exterior of the structure: 11

Number of historic windows on the structure:

Number of existing replacement/non historic windows: 1

Number of windows completely missing: 1 Number of windows to be replaced: 1

Window #:	Existing Condition (Excellent, Good, Fair, Poor):	Describe any deficiencies:	Photo #:	Historic (50 years or older):
W1	Poor		10a	
W2	Poor		10b	
W3	Poor		10c	
W4	Poor		10c	
W5	Poor		10d	
W6	Poor		10e	
W7	Poor		10f	
W8	Poor		10g	
W9	Poor		3c	
W10	Poor		3f	

If you have uestions regarding the re-uirements on this application or process please contact a member of the Par-City Planning taff at 4 1 or visit us online at www.par-city.org. pdated 1 / 14.

Photo 9a: East entry door D1




Photo 9b: South entry door D2



If you have uestions regarding the re-uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

Photo10a: Bedroom window W1



Photo 10b: Bedroom window W2



If you have uestions regarding the re-uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

Photo 10c: Living room window W3 and W4



Photo 10d: Living room window W5



If you have uestions regarding the re-uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

Photo 10e: Living room window W6



Photo 10f: Kitchen window W7



If you have uestions regarding the re-uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

Photo 10g: Bathroom window W8



If you have uestions regarding the re-uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

11. Interior Photographs

Use this section to describe interior conditions. Provide photographs of the interior elevations of each room. (This can be done by standing in opposite corners of a square room and capturing two walls in each photo.)

Element/Feature:	Interior	
This involves:	☐ An original part of the building	
	A later addition	Estimated date of construction: After 197

Describe existing feature:

There are no original trim on doors and windows. There are several types of base and casing, all installed after 197 . ee 9. Doors and 1 . indows photos.

Existing Condition: Excellent Good Fair Poor

Photo Numbers: 11a, 11b, 11c Illustration Numbers: AB.1

Photo 11a: Kitchen cabinets



If you have uestions regarding the re uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

Photo 11b: Kitchen cabinets



Photo 11c: Kitchen



If you have uestions regarding the re-uirements on this application or process please contact a member of the Par City Planning taff at 4 1 or visit us online at www.par city.org. pdated 1 / 14.

Shen Engineers, Inc. Structural/Seismic Consultants

3335 S. 900 E., Suite 250 Salt Lake City, UT 84106 801.466.2625 801.466.2656fax 7949 Silverton Ave., Suite 915 San Diego, CA 92126 858.699.2275 801.466.2656fax

Sept. 7, 2010

Mr. Jonathan DeGray, AIA Jonathan DeGray - Architect P.O. Box 1674 Park City, Utah 84060

Subject:

Physical Condition Report of Park City House

At 115 Sampson Ave. Park City, Utah

To Whom It May Concern:

We have performed a site investigation of the building and have done some structural calculations to determine the adequacy of the building. The capacity check of structural members is based on the 2009 International Building Code(2009IBC). That would give us idea that how good the members are. This building is a historical building. Based on historical building code, if the members have more than 50% of capacity of what the code is required, the members are ok.

The follows are the conclusions:

- Most of the existing roof joists are real 2x4 at 24" o.c. on 12:12 slope with 1x6 collar ties
 @ 48" o.c.. They are less than 50% capacity of the code. They need to be upgraded by
 either sister them with the better joist members or replaced with new roof joists.
- The existing roof deck is 1x wood plank installed particular to the existing joists. It
 doesn't have any capacity of shear diaphragm value. Suggest to install a layer of new
 5/8" plywood or OSB with 10d @ 6" o.c. nailing.
- The existing attic floor joists are guessed to be 2x8 @ 16" o.c. Suggest to install new 2x8 @ 16" o.c. to sister the existing floor joists.
- 4. The existing crawl space floor joists are real 2x6 at 24" o.c. The floor sheathing is 1x6 plank. They are less than 50% capacity of the code. They need to be upgraded by either sister them with the better joist members or replaced with new floor joists.
- The front deck was built with 2x4 joists @ 24" o.c. with 2x8 beam to support them. The
 posts are 4x4s.
- All the existing headers need to be upgraded.
- 7. The existing exterior walls are just 1x12 planks vertical plus 1x6 planks horizontal with ½" Celutex(fiber board) outside. The exterior walls are all not strong enough for wind, seismic or gravity loads. Suggest that new 2x4 df#2 or better stud walls at 16" o.c. need to be installed around the exterior walls. New shear wall sheathing and holdowns also shall be installed to develop a new lateral system.

 The existing building doesn't have any footings. New concrete footing and foundation need to be poured for supporting the existing building and forming the frost depth of 40".
 And the proper reinforcing needs to be placed.

Since the existing exterior walls are built of 1x10 boards only. No wood stud framing has been used in the walls. We suggest that if the home is to be lifted or moved to install a new foundation that doing so as a single unit may present a safety concern unless extensive shoring is installed. It would be safer to panelize the walls of the home and move them that way.

We hope that the information contained herein will assist you in your planning efforts. Should you have any further questions, please feel free to contact our office at your convenience.

Best Regards,

Henry Shen, SE, Shen Engineers, Inc.

3335 S. 900 E., Suite 250 Salt Lake City, Utah 84106

Shen Engineers, Inc. Structural/Seismic Consultants

2225 E. Murray Holladay Rd., Suite 208 Holladay, UT 84117 801.277.2625 801.277.2626fax 100 S. Alameda St., Suite 463 Los Angeles, CA 90012 858.699.2275 801.277.2626fax

April 26, 2018

Mr. Jonathan DeGray, AIA Jonathan DeGray - Architect P.O. Box 1674 Park City, Utah 84060

Subject:

Physical Condition Report of Park City House

At 115 Sampson Ave. Park City, Utah

To Whom It May Concern:

We have performed a site investigation of the building on April 24, 2018 with the architect Jon DeGray. The conclusions on the house are as follows:

- 1. The building was temporally shored not long ago (We guess the temporary shoring was installed within 2 to 5 years) with 2x6 stud walls, beams, columns and footings.
- 2. The existing roof joists are 2x6 at 24" on center on a sloped roof spanning 8'-0" to 12'-0". The 12'-0" roof joists are 18% capacity of the code. The 8'-0" roof joists are 28% capacity of the code. They need to be upgraded or replaced with new roof joists. We suggest reframing roof ridge and valley beams and installing new roof joists.
- 3. The existing roof deck is 1x wood plank installed perpendicular to the existing joists. It doesn't have any capacity of shear diaphragm value. Suggest installing new 5/8" plywood or OSB with 10d @ 6" on center nailing.
- 4. The existing (crawl space) floor joists are 2x6 @ 24" on center spanning 8'-0" to 12'-0. Most of them were totally rotted out. They have to be replaced.
- All the existing headers need to be upgraded. We will review each one of them when design is available.
- 6. The existing exterior walls are 1x12 installed vertically with 1x6 planks installed horizontally. The exterior walls have no capacity for wind, seismic or gravity loads. Some of the wood stud walls retain the dirt. 75% of the exterior walls were rotted out and have to be re-built.
- 7. The existing building doesn't have any footings. The existing foundation walls were built with wood piles and sand stone. 90% of them were rotted out. We suggest tearing off the existing foundation walls. New reinforced concrete footing and foundation walls need to be poured for supporting the existing building and forming the frost depth of 40" minimum.

- 8. Overall, the whole house is rotted out. The maximum differential settlement on the building is about one foot. To lift or temporarily shore them becomes to be impossible.
- 9. We suggest panelizing the existing building and re-build the house.

We hope that the information contained herein will assist you in your planning efforts. Should you have any further questions, please feel free to contact our office at your convenience.

Best Regards,

Henry Shen, SE,

Shen Engineers, Inc. ATE OF UT

2225 East Murray Holladay Road, Suite 208

Holladay, Utah 84117



Building • Engineering • Planning

April 27, 2018

Joseph Sponholz and Nancy Bronstein Silver Potato LLC 25 E End Ave #8C New York, NY 10028

CC: Jon Degray, Architect; Anya Grahn, Park City Municipal Corporation

RE: 115 Sampson Avenue, Park City, UT 84060

Dear Joseph and Nancy,

Please be advised that the historic structure located at 115 Sampson Avenue, was found to be hazardous or dangerous, pursuant to Section 116.1 of the International Building Code. A Notice and Order to vacate and repair the structure due to its general dilapidated state was issued on April 10, 2013. Following the Notice and Order, the building was then mothballed in 2011.

Planning and Building Department staff visited the site on April 16 and 18, 2018. At that time, we observed the following conditions:

- Due to the lack of foundation beneath the historic house, the floor structure has slumped. This
 has caused the walls to buckle and settle unevenly.
- The hillside has settled across the back of the historic house, accelerating the deterioration of
 the west wall; a stone cellar on the west side of the house is no longer accessible from the
 interior of the house. Further wood rot and deterioration can be seen along the roofline, with
 rotted and missing eaves, rusted metal roofing, and deteriorated dormers. Moisture has
 entered the structure through the deteriorated roofing and rotted wood siding.
- The previous owner had made significant alterations to the historic house including adding aluminum windows and doors, aluminum siding and faux vinyl brick siding, and skylights on the front porch. These improvements are in varying degrees of deterioration.
- During the site visits, the applicant and staff discussed panelizing the north, south, and east
 walls of the historic house. Significant portions of these walls were removed in order to expand
 the window openings on the east façade from single windows to large picture windows. These
 larger openings may compromise the structural integrity of the walls.
- The porch structure and decking has deteriorated as it sits directly on the soil on the south elevation of the house. The porch has settled unevenly and has begun to pull away from the house.

Due to the structural instability of the house, as well as the extent of the deterioration of the original materials, I find that the safest approach is to panelize the historic house.

SAT

Dave Thacker

Chief Building Official