HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

| 1 IDENTIFICATION | | | | | | | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|--|--|--|--|
| Name of Property: | | | | | | | | |
| Address: 501 Woodside Avenue | e. | AKA: | | | | | | |
| City, County: Park City, Summit | | | | | | | | |
| | | | |) | | | | |
| Current Owner Name: Ivan Knauer & Margaret Sheehan Parent Parcel(s): PC-340 Current Owner Address: 1237 Meyer Ct, McLean, VA 22101 | | | | | | | | |
| Legal Description (include acreage): 0.05 acres; LOT 1 501 WOODSIDE SUBDIVISION AKA 501 WOODSIDE AVENUE SUBDIVISION. | | | | | | | | |
| 2 STATUS/USE | | | | | | | | |
| Property Category ☑ building(s), main ☐ building(s), attached ☐ building(s), detached ☐ building(s), public ☐ building(s), accessory ☐ structure(s) | Evaluation* Reconstruction Use □ Landmark Site Date: Original Use: Residential □ Significant Site Permit #: Current Use: Residential □ Not Historic □ Full □ Partial *National Register of Historic Places: ☑ ineligible □ listed (date:) | | | | | | | |
| 3 DOCUMENTATION | | | | | | | | |
| Photos: Dates □ tax photo: □ prints: 1995 & 2006 □ historic: c. □ original bui □ sewer perm □ prawings and Plans □ measured floor plans □ site sketch map □ city director □ original plans: □ original plans: □ other: □ original plans: □ other: □ libiliographical References (books, articles, interviews, places) □ Sanborn M □ measured floor plans □ obituary incomplete original plans: □ original plans: □ other: □ newspaper □ park City Historic Architecture □ University of Utah Graduate School of Architecture and McAlester, Virginia and Lee. A Field Guide to American Hourent Roberts, Allen. "Final Report." Park City Reconnaissance Lee Roper, Roger & Deborah Randall. "Residences of Mining Both Historic Places Inventory, Nomination Form. 1984. | | | nit ceers ceers cleers cle | se City: 2007. ake City, Utah: 1991. pf, 1998. 5. | | | | |
| 4 ARCHITECTURAL DESCRIPTION & INTEGRITY | | | | | | | | |
| Building Type and/or Style: T/L cottage / vernacular style No. Stories: 2 | | | | | | | | |
| Additions: ☐ none ☐ minor ☑ major (describe below) Alterations: ☐ none ☐ minor ☑ major (describe below) | | | | | | | | |
| Number of associated outbuilding | _ | ures: accesso | ry building(s), # _ | ; □ structure(s), # | | | | |
| General Condition of Exterior Materials: | | | | | | | | |

Researcher/Organization: Dina Blaes/Park City Municipal Corporation Date: November, 08

| | ☑ Good (Well maintained with no serious problems apparent.) | | | | | | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|--|--|--|--|--|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| | ☐ Fair (Some problems are apparent. Describe the problems.): | | | | | | | |
| | ☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.): | | | | | | | |
| | □ Uninhabitable/Ruin | | | | | | | |
| Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.): Site: Narrow lot, terraced front and side yards. Driveway runs along the south side of the lot. Public stairway runs along south side of lot. Large evergreen tree, informal landscapingperennials, native species, grasses Foundation: Concrete | | | | | | | | |
| | | | | | | | Walls: Basement addition clad in stone veneer. Main floor clad in drop siding. Shed roof porch extends from within principal roof and is supported by heavy square column. Heavy rail extends across front of house along edge of extended porch/deck over garage. | |
| | Roof: Cross-wing form sheathed in asphalt shingles. Shed roof also sheathed in asphalt shingles. | | | | | | | |
| | Windows: single and paired double-hung window units. | | | | | | | |
| Essential Historical Form: ☑ Retains □ Does Not Retain, due to: | | | | | | | | |
| Loc | ation: ☑ Original Location ☐ Moved (date) Original Location: | | | | | | | |
| Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including datesknown or estimatedwhen alterations were made): The T/L cottage frame house sits above | | | | | | | | |

Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including dates--known or estimated--when alterations were made): The T/L cottage frame house sits above a basement addition with garage. Early photographic evidence is not available, but a 1995 photograph shows significant incompatible alterations were made in the past. The asbestos siding seen in the 1995 photograph has been replaced with wood drop siding, though it is not clear if the siding is the original or was milled to match the original. Window openings have been made that are compatible with the typical configurations seen on park City mining era homes and single and paired double-hung windows have been used. The porch, which would typically be an extended or dropped shed roof element, in this case projects from within the principal roof and is supported by a wider than typical porch support. A rear addition has been constructed and utilizes compatible window openings, materials, and roof forms. This may have been a partial or complete reconstruction. The changes are significant and diminish the site's original character.

Setting (The physical environment--natural or manmade--of a historic site. Describe the setting and how it has changed over time.): The setting, based on a 1995 photograph, was a gradual rise from front to back with a short retaining wall at the street front. The house was situated on a relatively level building pad. The setting has been significantly altered to accommodate a basement addition with garage.

Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): Much of the physical evidence from the period that defines the typical Park City mining era home has been altered and, therefore, lost.

Feeling (Describe the property's historic character.): The physical elements of the site, in combination, do not effectively convey a sense of life in a western mining town of the late nineteenth and early twentieth centuries.

Association (Describe the link between the important historic era or person and the property.): The "T" or "L" cottage (also known as a "cross-wing") is one of the earliest and one of the three most common house types built in Park City during the mining era; however, the extent of the alterations to the main building diminishes its association with the past.

The extent and cumulative effect of alterations to the site render it ineligible for listing in the National Register of Historic Places.

5 SIGNIFICANCE

| Architect: ☑ Not Known □ | ☐ Known: | (source:) | Date of Construction: c. 1904 ¹ | | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------|----------------------------------------------------------|--|--|--|
| Builder: ☑ Not Known □ | Known: | (source:) | | | | |
| The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below: | | | | | | |
| Historic Era: □ Settlement & Mining B Mature Mining Era (18 □ Mining Decline & Eme | 394-1930) | , | try (1931-1962) | | | |
| Park City was the co | enter of on | e of the top three | metal mining districts in the state during Utah's mining | | | |

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's houses are the largest and best-preserved group of residential buildings in a metal mining town in Utah. As such, they provide the most complete documentation of the residential character of mining towns of that period, including their settlement patterns, building materials, construction techniques, and socio-economic make-up. The residences also represent the state's largest collection of nineteenth and early twentieth century frame houses. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining community.²

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: East elevation. Camera facing west, 2006.

Photo No. 2: Southeast oblique. Camera facing northwest, 2006.

Photo No. 3: Southeast oblique. Camera facing northwest, 1995.

¹ Summit County Tax Assessor.

² From "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.





