HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION	7,444 0111	WOMON AL CON	Oravinon (10 c			
Name of Property: Address: 2414 MONITOR DR (BARN) City, County: Park City, Summit County, Utah Current Owner Name: PREUS DOROTHEA STROUGH TRUSTEE Current Owner Address: 2414 MONITOR DR, PARK CITY, UT 84060 Legal Description (include acreage): LOT 99 HOLIDAY RANCHETTES SUBDIVISION, 2.45 AC						
2 STATUS/USE						
Property Category ☑ building(s), main ☐ building(s), attached ☐ building(s), detached ☐ building(s), public ☐ building(s), accessory ☐ structure(s)	Evaluation* ☑ Landmark S ☑ Significant S ☑ Not Historic *National Region Root storage of Listed (date	Site Date: Site Permit Full Ster of Historic Poellar.	☐ Partial	<u>Use</u> Original Use: Residential Current Use: Residential gible - House ☑ eligible - Barn an	nd	
3 DOCUMENTATION						
Blaes, Dina & Beatrice Lufkin. "Fina Carter, Thomas and Goss, Peter. University of Utah Graduate Sc Lufkin, Beatrice & Dina Blaes. "Mor 2006. McAlester, Virginia and Lee. A Fiel Roberts, Allen. "Final Report." Park	□ abs □ tax □ orig □ sew ☑ Sar □ obit □ city ey □ cen □ biog □ new oks, articles, inter chool of Architect nitor Barn." Intens dd Guide to Americated Guide to Americates "Residences of N	ctract of title card pinal building perror ver permit aborn Maps cuary index directories/gazer sus records graphical encyclo vspapers erviews, etc.) Attactive Historic Building chitecture, 1847-18 ure and Utah State sive Level Survey Sican Houses. New Jance Level Survey Mining Boom Era, F	nit tteers pedias ach copies of the copie	Salt Lake City, Utah: riety, 1991. Form. Park City Municipal Corporation. . Knopf, 1998.		
4 ADCUITECTUDAL DESCRIPTION & INTEGRITY						
4 ARCHITECTURAL DESCRIPTION & INTEGRITY						
Building Type and/or Style: Bungalow No. Stories: 1 ½ Additions: □ none □ minor ☑ major (describe below) Alterations: □ none □ minor ☑ major (describe below)						
Researcher/Organization: Preservation Solutions/Park City Municipal Corporation Date: 12-2008						

Number of associated outbuildings and/or structures: ☑ accessory building(s), #2; ☐ structure(s), #					
General Condition of Exterior Materials:					
☑ Good (Well maintained with no serious problems apparent.)					
☐ Fair (Some problems are apparent. Describe the problems.):					
☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):					
☐ Uninhabitable/Ruin					
Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.): Site: Main house, root storage cellar built into the hill behind the house and large barn structure.					
Foundation: Not verified.					
Walls: Horizontal wood siding.					
Roof: Low-pitched hipped roof (original) - asphalt shingles. Cross-wing and pop-top gable addition also asphalt shingle.					
Windows/Doors: Chicago-style, double-hung sash, and casement type.					
Essential Historical Form: ☑ Retains ☐ Does Not Retain, due to:					
Location: ☑ Original Location ☐ Moved (date) Original Location:					
Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including datesknown or estimatedwhen alterations were made): The 1½-story (originally one-story) frame bungalow house has been significantly altered. According to the Intensive Level Survey performed on the barn structure in 2006, the house was built c. 1918 and had its most recent alterationthe second floor additionin 2003-04. The changes are significant and diminish the site's original character.					
Setting (The physical environmentnatural or manmadeof a historic site. Describe the setting and how it has changed over time.): The setting is rural with the three associated structureshouse, barn and root storage cellarset apart on the lot. The barn, assessed in 2006, is eligible for listing in the National Register of historic places though the house is not. The root storage cellar would also be eligible for listing in the NR. See "Monitor Barn" ILS files held by Park City Planning Department.					
Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): Much of the physical evidence from the period that defines the typical Park City mining era home has been altered and, therefore, lost.					
The barn and the root cellar retain the physical evidence and distinctive elements found during the mining era.					
Feeling (Describe the property's historic character.): The physical elements of the site, in combination, do not effectively convey a sense of life in a western mining town of the late nineteenth and early twentieth centuries, though the barn and root cellar do reinforce the site's historic character.					
Association (Describe the link between the important historic era or person and the property.): The bungalow is a common house type built in Utah curing the early 20th century; however, this extent and cumulative affect of changes made to the house render it ineligible for listing in the National Register.					
5 SIGNIFICANCE					
Architect: ☑ Not Known ☐ Known: (source:) Date of Construction: c. 1918 ¹					

¹ Park City Municipal Corporation Planning Department files.

Builder: ☑ Not Known	☐ Known:	(source:)
The site must represent significant under one of t		part of the history or architecture of the community. A site need only be as listed below:
Historic Era: □ Settlement & Minin Mature Mining Era □ Mining Decline & E	(1894-1930)	
Park City was th	e center of or	ne of the top three metal mining districts in the state during Utah's mining

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's houses are the largest and best-preserved group of residential buildings in a metal mining town in Utah. As such, they provide the most complete documentation of the residential character of mining towns of that period, including their settlement patterns, building materials, construction techniques, and socio-economic make-up. The residences also represent the state's largest collection of nineteenth and early twentieth century frame houses. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining community.²

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: Main house - side elevation, 2006.

Photo No. 2: Barn - "Monitor Barn", 2006.

Photo No. 3: Root Storage Cellar, 2006.

See additional photographs prepared as part of the 2006 Intensive Level Survey of the "Monitor Barn."

² From "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

HISTORIC SITE FORM

UTAH OFFICE OF PRESERVATION

1 IDENTIFICATION

Name of Property: Monitor Barn

Address: 2414 Monitor Drive Twnshp: 2S Range: 4E Section: 6 & 9

City, County: Park City, Summit County UTM:

Current Owner Name: Dorothea Strough Preus, Jr. USGS Map Name & Date: Park City West

1955, Rev. 1975

Current Owner Address: 2414 Monitor Drive, Park City, UT 84060 Tax Number: HR-99Xxx

Legal Description (include acreage): Lot 99, Holiday Ranchettes (Cont. 2.45 acres)

2 STATUS/USE

<u>Property Category</u>	<u>Evaluation</u>	<u>Use</u>	
$\underline{\mathbf{x}}$ building(s)	<u>x</u> eligible/contributing	Original Use:	Agricultural Outbuilding
structure	_ ineligible/non-contributing	Course out I la o	Desidential Outhwilding
site object	_ out-of-period	Current Use:	Residential Outbuilding
_ 00,000			

3 DOCUMENTATION

Photos: Dates	Research Sources (check all sources of	consulted, whether useful or not)
<u>x</u> <i>slides</i> : 2006	$\underline{\mathbf{x}}$ abstract of title	<u>x</u> city/county histories
<u>x</u> prints: 2006	x tax card & photo	<u>x</u> personal interviews
<u>x</u> historic: 1989 tax photo	<u>x</u> building permit	<u>x</u> USHS Library
	_ sewer permit	<u>x</u> USHS Preservation Files
<u>Drawings and Plans</u>	<u>x</u> Sanborn Maps	USHS Architects File
_ measured floor plans	_ obituary index	x LDS Family History Library
$\underline{\mathbf{x}}$ site sketch map	_ city directories/gazetteers	<u>x</u> <i>local library:</i> Park City Historical
_ Historic American Bldg. Survey	<u>x</u> census records	Society and Museum
_ original plans available at:	_ biographical encyclopedias	<u>x</u> university library(ies): Marriott
_ other:	newspapers	Library, University of Utah

Bibliographical References (books, articles, interviews, etc.)

Attach copies of all research notes, title searches, obituaries, and so forth.

Carter, Thomas and Roger Roper. Of Work and Romance: Discovering Utah Barns. University of Utah Graduate School of Architecture. Western Regional Architecture Program, # 9. Salt Lake City, UT: 1999. Coleman, Bill. Telephone interview with author, November 27, 2006.

Hampshire, David, Martha Sonntag Bradley and Allen Roberts. *A History of Summit County*. Utah Centennial History Series. Utah State Historical Society and the Summit County Commission. Salt Lake City: Utah State Historical Society, 1998.

Kimball, Gary. Telephone interview with author, November 22, 2006.

Mangum, Garth L. "Welfare Farms." Encyclopedia of Mormonism. Vol. 4. New York: Macmillan, 1992.

Rudd, Glen L. Pure Religion: The Story of Church Welfare Since 1930. Salt Lake City: Church of Jesus Christ of the Latter-day Saints, 1995.

Researcher/Organization:	Rootrica Luflein	Dina Place	/ Park City Municipal Cor	noration	Date:	2006
Nesearcher/Organization.	Dealife Luikiii-	– Dilla Diacs	/ Laik City Miulicidal Col	DOIALION	Daie.	2000

4 ARCHITECTURAL DESCRIPTION

Building Style/Type:	Twentieth Century: Other / Barn: Other		No. Stories: _	1		
Foundation Material:_	concrete			Wall Material(s):_	wooden drop siding	
Additions:none <u>x</u>	minor _ major (d	escribe below)	Alterations:	none_x_minor_	_ major (describe below)	
Number of associated o	utbuildings <u>3</u>	_ and/or structi	ıres <u>0</u> .			
Briefly describe the prin Use continuation sheets	1	ditions or altera	tions and their	dates, and associate	ed outbuildings and struct	tures.

The building under study, the Monitor Barn, is a rectangular frame gable-roofed implement shed built in 1928 with the narrow end to the street on a large residential lot in the middle of a platted housing subdivision, Holiday Ranchetts,² north of Kearns Boulevard in Park City. Painted weathered wooden drop siding covers most of the wall surfaces but some new matching siding has been added during the 2006 renovation. The shed is roughly 26 feet wide and 65 feet deep³ and is parallel to the blacktopped driveway leading to the house. Tax assessor records refer to it as an "old milk barn" in 2005 yet an earlier tax assessor record has a c. 1928 26' x 62' implement shed and shop with a concrete floor that is most likely the current structure.4

The barn is an eligible/contributing outbuilding associated with a noncontributing/altered primary structure. The historic house on the property was built c. 1918,⁵ and has had several significant additions that altered its historic integrity; the most recent changes in 2003-4 included a second floor addition. Two other structures on the property include a contributing root storage cellar (called a bunker/shed in the site drawings from the 2003 remodel) directly to the north of the house and a most likely noncontributing small livestock shelter⁶ in the field to the south.

The barn has a poured concrete floor with a raised foundation. The horizontal window openings on the north and south elevations have six pane vinyl replacement windows in uniformly spaced openings. A new door opening has been added to the south elevation, with six windows to the west and one to the east of the door. Both north and south elevations have exposed rafter tails on the roof edge.

The east elevation is dominated by a 2006 two-car overhead vinyl garage door. The door is segmented with decorative x-braces stamped on the surface. A small fixed pane window is located in the gable end with a curved metal fixture light above.

The west elevation, the primary façade that faces the street, has two diagonal wood-plank doors that are hung from the top and slide horizontally. Decorative double X-braces painted in a contrasting color were added in the 2006 renovation. The gable end fixed pane window and light above appear identical to the ones on the east elevation.

The building was remodeled and painted in 2006 and the above description of the barn is as of November 2006. The parcel is in the middle of a built-out subdivision development with primarily single dwellings from the 1970s to the present. The shed is set back on the lot and the house is behind it with a large expanse of blacktop for parking between the two structures and a long driveway along the north side of the property. The barn and the root cellar retain their historic integrity and are eligible/contributing buildings.

¹ 2.45 acres.

² Also spelled Ranchettes in Summit County Recorder's Office documents

³ According to Summit County Assessor's Office records, 1-28-05.

⁴ The above record also lists a large barn and milking stanchions, both of which have been removed or were located outside of this parcel.

⁵ Park City Municipal Corporation Planning Department files, 2003 design review for remodel of residence.

⁶ The livestock shelter does not appear on the site map for the 2003 remodel nor is it enumerated in the tax assessor records so it may have been moved to the site. Further research would be needed to determine its status.

Architect/Builder: unknown		Date of Construction: c. 1928		
Historic Themes: Mark themes rela (see instructions for deta		S''' or C''' ($S = significant$, C	C = contributing).	
<u>C</u> Agriculture	Economics	Industry	Politics/	
Architecture	Education	Invention	Government	
Archeology	Engineering	Landscape	<u>C</u> Religion	
Art	Entertainment/	Architecture	Science	
Commerce	Recreation	Law	<u>C</u> Social History	
Communications	Ethnic Heritage	Literature	Transportation	
Community Planning	Exploration/	Maritime History	Other	
& Development	Settlement	Military		
Conservation	Health/Medicine	Parforming Arts		

Write a chronological history of the property, focusing primarily on the original or principal owners & significant events. Explain and justify any significant themes marked above. Use continuation sheets as necessary.

The barn/equipment shed most likely was constructed in 1928 as an outbuilding on the privately-held farm. The Church of Jesus Christ of Latter-day Saints (LDS or Mormon) began purchasing farmlands in Utah in the late 1930s in response to the economic hardships of the Great Depression. By the 1940s stakes were purchasing farms as approved welfare projects and their members ran the farms in additional to their usual occupations. These farms were often quite a distance from the stake itself. The welfare farm movement was at its height of popularity in the 1950s and 1960s. By 1990 the LDS church only owned 160 welfare farms and 250 reserve farms. The majority were located in Utah, Idaho, California and Arizona.

The LDS Holladay Stake in Salt Lake City probably purchased this property in a larger piece from an individual during its welfare farm era and owned this property until it was sold to the Greater Park City Company in the early 1970s. It was known as the Holladay Stake Welfare Farm.

A consortium of the Greater Park City Company, its mother corporation, the Royal Street Corporation (a Louisiana company), and the Western Mortgage Company acquired a large (170.980 acre) piece of property which they developed into a subdivision called Holiday Ranchettes in 1974. This shed is located on Lot 99 of the subdivision. The Royal Street Corporation of New Orleans bought the Park City Resort, as is was known then, in February of 1971 and sold it three years later to Alpine Meadows of Tahoe, California in 1974. Royal Street had created the Greater Park City Company to hold its resort holdings but the company ran into financial difficulties in the mid 1970s.

Kathleen Joan Cartier purchased the property in 1977 and owned it until 2001 when she sold it to Bradley S. and Jillian A. Scott. The Scotts transferred the title to Dorothea Preus, the current owner, in 2003.

The existing house was extensively remodeled in 2003-4. It was built c. 1918⁹ but is an ineligible non-contributing structure because of the remodeling and additions. The barn and the root cellar retain their historic integrity and are eligible/contributing buildings.

-

⁷ The date is from Summit County tax assessor records.

⁸ A stake is an organizational unit of the LDS church which is comprised of a number of wards, the smallest unit, which are similar to a diocese and a parish in the Catholic or Episcopal churches.

⁹ Summit County tax assessor records.





