HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION								
Name of Property: Milton & Mi	nerva Th	nomas House						
Address: 445 Park Ave			AKA:					
City, County: Park City, Summi	t County,	, Utah	Tax Numb	<i>per:</i> PC-58				
Current Owner Name: WEISEN	NBURG V	VILSON T & LC	ORILEE G H/W (JT)	Parent Parcel(s):				
Current Owner Address: 5881 I	LANCEF	IELD DR, HUN	TINGTON BEACH, CA	92649				
Legal Description (include acre	age) LO	TS 12 & 13 BL	(4 PARK CITY SURVE	Y; Acres 0.09				
2 STATUS/USE								
<u>Property Category</u> ☑ building(s), main	Evaluat	<u>tion*</u> dmark Site	<u>Reconstruction</u> Date:	<u>Use</u> Original Use: Residential				
☐ building(s), main		ificant Site	Permit #:	Current Use: Residential				
☐ building(s), detached	□ Not I	Historic	☐ Full ☐ Partial					
☐ building(s), public ☐ building(s), accessory								
□ structure(s) *National Register of Historic Places: □ ineligible □ eligible								
□ listed (date:)								
3 DOCUMENTATION								
Photos: Dates				consulted, whether useful or not)				
☑ tax photo: ☐ abstract of title ☑ city/county histori								
☑ prints: ☐ historic: c.			ding permit	□ personal interviews□ Utah Hist. Research Center				
□ sewer permit □ USHS Preservation Files								
<u>Drawings and Plans</u>								
☐ site sketch map ☐ city directories/gazetteers ☐ Park City Hist. Soc/Museum								
☐ Historic American Bldg. Survey☐ census records☐ university library(ies)☐ biographical encyclopedias☐ other:								
□ other: □ newspapers								
Bibliographical References (books, articles, interviews, etc.) Attach copies of all research notes and materials.								
Blaes, Dina & Beatrice Lufkin. "Fin								
Carter, Thomas and Goss, Peter.	Utah's His	storic Architecture	e, 1847-1940: a Guide. Sa	alt Lake City, Utah:				
University of Utah Graduate S McAlester, Virginia and Lee. <i>A Fie</i>								
Roberts, Allen. "Final Report." Parl	k City Rec	connaissance Lev	vel Survey. Salt Lake City:	1995.				
Historic Places Inventory, Non			om Era, Park City - Thema	atic Nomination." National Register of				
4 ARCHITECTURAL DESCRI	PTION &	INTEGRITY						
Building Type and/or Style: Hal	l Darlar L	Journ		No. Stories: 1 ½				
5 7.			Ntorations: □ none - ☑ r					
Additions: ☐ none ☑ minor ☐	•			• •				
	•		accessory building(s),	#; □ structure(s), #				
General Condition of Exterior Materials:								

Researcher/Organization: Preservation Solutions/Park City Municipal Corporation Date: 12-2008

	☑ Good (Well maintained with no serious problems apparent.)
	☐ Fair (Some problems are apparent. Describe the problems.):
	☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):
	□ Uninhabitable/Ruin
	erials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. ribe the materials.): Site: Out of period detached garage.
	Foundation: Stone.
	Walls: Drop siding.
	Roof: Gable roof form sheathed with standing seam metal materials.
	Windows/Doors: Double-hung sash type and multi-pane French doors in dormer.
Esse	ential Historical Form: ☑ Retains □ Does Not Retain, due to:
Loca	ation: ☑ Original Location ☐ Moved (date) Original Location:
from has	ign (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations the original design, including datesknown or estimatedwhen alterations were made): The 1 ½-story frame hall-parlor house been altered only slightly from what is described in the national register nomination form (see Structure/Site m 1983).
shed	rations include a replacement door that is not compatible with the house and the addition of a pediment on the d roof projecting from the dormer. The Sanborn Insurance maps indicate a series of additions on the rear of the se, their existencein whole or partwas not verified.
setti	ing (The physical environmentnatural or manmadeof a historic site. Describe the setting and how it has changed over time.): The ing has not been altered from what is described in the national register nomination or seen in early tographs.
elem simp	kmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive ents.): The physical evidence from the period that defines this as a typical Park City mining era house are the ole methods of construction, the use of non-beveled (drop-novelty) wood siding, the plan type, the simple roof n, the informal landscaping, the restrained ornamentation, and the plain finishes.
	ling (Describe the property's historic character.): The physical elements of the site, in combination, convey a sense of n a western mining town of the late nineteenth and early twentieth centuries.
earli	ociation (Describe the link between the important historic era or person and the property.): The Hall-Parlor house form is the iest type to be built in Park City and one of the three most common house types built in Park City during the ing era.
Res	s site was listed on the National Register of Historic Places in 1984 as part of the <i>Park City Mining Boom Era idences Thematic District</i> . It was built within the historic period, defined as 1872 to1929 in the district nination, and retains its historic integrity. As a result, it meets the criteria set forth in LMC Chapter 15-11 for ignation as a Landmark Site.
5 8	BIGNIFICANCE
Arch	nitect: ☑ Not Known ☐ Known: (source:) Date of Construction: c. 1880 ¹

¹ National Register nomination.

Builder: ☑ Not Known ☐ Known: (source:)
The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below:
 1. Historic Era: ☑ Settlement & Mining Boom Era (1868-1893) ☐ Mature Mining Era (1894-1930) ☐ Mining Decline & Emergence of Recreation Industry (1931-1962)

Park City was the center of one of the top three metal mining districts in the state during Utah's mining boom period of the late nineteenth and early twentieth centuries, and it is one of only two major metal mining communities that have survived to the present. Park City's houses are the largest and best-preserved group of residential buildings in a metal mining town in Utah. As such, they provide the most complete documentation of the residential character of mining towns of that period, including their settlement patterns, building materials, construction techniques, and socio-economic make-up. The residences also represent the state's largest collection of nineteenth and early twentieth century frame houses. They contribute to our understanding of a significant aspect of Park City's economic growth and architectural development as a mining community.²

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.

Photo No. 1: East elevation. Camera facing west, 2006.


Photo No. 2: Northeast oblique. Camera facing southwest, 2006.

Photo No. 3: Northeast oblique. Camera facing southwest, 1983.

Photo No. 4: Southeast oblique. Camera facing northwest, tax photo.


² From "Residences of Mining Boom Era, Park City - Thematic Nomination" written by Roger Roper, 1984.

Class Dimensions Cu. Ft. Sq. Ft. Factor Totals X	Location						
Stories Dimensions Cu. Ft. Sq. Ft. Factor Totals X	Kind of Bldg. RES		St. No.	445	Park	A	ve
X X X X X X X X X X	Class5	Ту	oe 123 4. (Cost \$			_ X%
Storm Sash—Wood D. S. Metal D. S.	Stories Dimensions		Cu. Ft.	Sq. Ft.	Facto	r	. Totals
Description of Buildings Foundation—Stone Cone. None Ext. Walls SID ING Roof Type Call Mtl. Pat Dormers—Small Med. Large I PATA Bays—Small Med. Large Bays—Small Med. Large Bays—Small Med. Large Bays—Small Med.	x x			83	2	\$	2344
Gar.—Carport x Fir. Walls Cl. Description of Buildings Foundation—Stone Conc. None Ext. Walls SlD II Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Rear I Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Mtl. Clgs. Rear I Conc. None Ext. Walls Clgs. Additions Mtl. Clgs. Rear I	x x				/		
Description of Buildings Foundation—Stone Conc. None Ext. Walls SID INC. Insulation—Floors Walls Clgs. Roof Type Mtl. Dormers—Small Med. Large Porches—Front Porches—Front Porches—Front Planters Rear Porch Metal Awnings Mtl. Rail Basement Entr. Planters Cellyd-Bsmt. 4½ ½ ½ % % Full Floor Latter Planters Cellyd-Bsmt. 4½ ½ ½ % % Full Floor Latter Planters Cellyd-Bsmt. 4½ ½ ½ % % Full Floor Latter Planters Cellyd-Bsmt. 5ink Toiled Wtr. Sftr. St. O.T. Dishwasher Garbage Disp. Built-in-Appliances Heat—Stove H.A. Seam Stkr. Blr. Oil Gas Coal Pipeless Radiant Air Cond. Finish—Fir Hd. Wd. Capat Hell Cabinets Mantels Tile—Walls Wainseot Floors Storm Sash—Wood D. S. ; Metal D. S. Total Additions Year Built Avg. Current Value Commission Adj. Total Additions Year Built Avg. Current Value Depr. Col. 12 2 3 4 5 6 3 7 % Current Value Minus Depr. Garage—Class Z Depr. 29/3% Carport—Factor Cars Floor Rain Additions Roof R Doors Total Additions Year Built Avg. Carport—Factor Cars Floor Rain Additions Roof R Doors							
Foundation—Stone Conc. None Ext. Walls SID IT Insulation—Floors Walls Cigs. Roof Type Gdb Mtl. Dat Dormers—Small Med. Large I NTJ Bays—Small Med. Large I NTJ Porches—Front I 30	Gar.—Carport x	_Flr	Walls _	Cl	_/_		and the same
Ext. Walls SID INC Insulation—Floors Walls Clgs. Roof Type Gall Mtl. Bays—Small Med. Large 1 NTV Bays—Small Med. Large 2 300 Rear 2 300 Metal Awnings Mtl. Rail Basement Entr. Planters Cellgd-Bsmt. — 1/4 1/4 1/4 1/4 1/4 1/4 1/4 1/4 1/4 1/4					Additions		
Insulation—Floors Walls Cigs. Roof Type Mtl. Pat Mtl. Pat Dormers—Small Med. Large 1 Path Porches—Front 130 2 2 2 300 Rear Porches—Front 130 2 2 2 300 Metal Awnings Mtl. Rail Basement Entr. @ Planters Cellsd-Bsmt. — 1/4 1/2 1/2 1/3 3/4 Full Floor Mtl. Rail Basement Entr.				None		\dashv	*
Roof Type Gal Mtl. Dat Large Nat Dormers—Small Med. Large Dormers—Small Med. Large Dormers—Small Med. Large Dorches—Front Dormers—Small Med. Large Dorches—Front Dormers—Small Med. Large Dorches—Front Dorches Dorc	N N			-		\dashv	
Dormers—Small Med. Large Pays - Small Med. Large Porches - Front Poor Porches - Front Poor Porches - Front Poor Porch Metal Awnings Mtl. Rail Basement Entr. Planters Cellsd-Bsmt ¼ ½ ½ ¾ ¼ Full Floor Lut Poor Porch Planters Plumbing Wtr. Sftr. Unfin. NTV Wtr. Sftr. Shr. Str. O.T. Dishwasher Garbage Disp. Built-in-Appliances Heat—Stove H.A. Seam Stkr. Blr. 209 Oil Gas Coal Pipeless Radiant Air Cond. Finish—Fir Ad. Wd. Other H.A. Wainseot Floors Storm Sash—Wood D. S. ; Metal D. S Wainseot Floors Storm Sash—Wood D. S. ; Metal D. S Bidg. Value Depr. Col. 12 3 4 5 6 3 7 % Current Value Malls Large Porch Poors		1		. /		-	
Bays - Small Med. Large Porches - Front 150 2 = 300 Rear Porches - Front 150 2 = 300 Rear Porch Porch Rear Porch Porch Rear Porch	U	1	1	/		\dashv	
Porches—Front 130 2 300 Rear		\		/	NTV	-	
Rear		1	Large	700	2	+	2
Porch Metal Awnings Mtl. Rail Basement Entr.		120			300	2	A
Metal Awnings	A STATE OF THE STA		/ -			+	Pa
Basement Entr. Planters Cellaf-Bsmt. — 1/4 1/2 1/3 3/4 Full Floor clutt 90 Bsmt. Apt. — Rooms Fin. — Untin. Attic Rooms Fin. — Untin. Plumbing Class — Tub — Trays Basin — Sink — Toiled — 1 Wtr. Sftr. — Shr. St. — O.T. Dishwasher — Garbage Disp. Built-in-Appliances Heat—Stove — H.A. — Steam — Stkr. — Blr. — 209 Oil — Gas — Coal — Pipeless — Radiant Air Cond. Finish— Fir — Hd. Wd. — Other Cabinets — Mantels Tile — Walls — Wainseot — Floors Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. —	17.13 B 717.1					-	7
Planters Cellar-Bsmt. — 14 1/2 1/3 3/4 Full Foor dut 90 Bsmt. Apt. — Rooms Fin. — Untin. Attic Rooms Fin. — Untin. Class — Tub — Trays Basin — Sink 1 — Toiled — 1 Wtr. Sftr. — Shr. St. — O.T. Dishwasher — Garbage Disp. Built-in-Appliances Heat—Stove — H.A. — Seam — Stkr. — Blr. — 209 Oil — Gas — Coal — Pipeless — Radiant Air Cond. Finish— Fir — Hd. Wd. — Other Cabinets — Mantels Tile — Walls — Wainseot — Floors Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Storm Sash— Wood D. — S. — ; Metal D. — S. — Bidg. Value Depr. Col. 12 3 4 5 6 3 7 % Current Value Minus Depr. \$ 13 1 3 Garage— Class — Depr. 29/3 3/6 Carport— Factor Cars — Floored — Walls — Roof R Doors			\ /			\dashv	1
Cellor-Bsmt. — 1/4 1/4 1/2 1/3 3/4 Full Foor dut 90 Bsmt. Apt. — Rooms Fin. — Unfin. Attic Rooms Fin. — Unfin. Class — Tub — Trays Basin — Sink — Toiled — Wr. Sftr. — Shr. St. — O.T. — Dishwasher — Garbage Disp. Built-in-Appliances — H.A. — Seam — Stkr. — Blr. — 209 Oil — Gas — Coa — Pipeless — Radiant Air Cond. Finish — Fir — Hd. Wd. — Other — Hd. Wd. — Other — Hd. Wd. — Other — Toors — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D. — S. — Storm Sash — Wood D. — S. — ; Metal D	1252 00		\/			\dashv	13
Bsmt. Apt. Rooms Fin. Unfin. Attic Rooms Fin. 7 Class Tub Trays Basin Sink Toiled Wtr. Sftr. Sink Toiled Wtr. Sftr. Sink Toiled Mtr. Sftr. Sink Toiled Trays Basin Sink Toiled Trays Built-in-Appliances Heat—Stove H.A. Seam Stkr. Blr. 209 Oil Gas Coa Pipeless Radiant Air Cond. Finish—Fir Hd. Wd. Other Cabinets Mantels Tile Walls Wainseot Floors Storm Sash—Wood D. S. ; Metal D. S. Total Additions Year Built Avg. Age Current Value Shows Adj. Neighbor - Record - Est. Remodel Year 156 Est. Cost Current Value Minus Depr. Garage—Class Depr. 2%3% Carport—Factor Cars L Floor Room Fin. Unfin. NTV Trays Trays Trays Total Addition NTV Total Addition NTV Total Additions Year Built Avg. Current Value Shows Adj. Current Value Minus Depr. \$ 1313		wa 25701	/\	1	0.0	\dashv	10
Attic Rooms Fin. Class Tub Trays Basin I Sink Toiled Wtr. Sftr. Shr. St. O.T. Dishwasher Garbage Disp. Built-in-Appliances Heat—Stove H.A. Steam Stkr. Blr. Oil Gas Coal Pipeless Radiant Air Cond. Finish—Fir Hd. Wd. Other Cabinets Mantels Tile — Walls Wainseot Floors Storm Sash— Wood D. S. ; Metal D. S. Total Additions Year Built Avg. Avg. Current Value Commission Adj. Bidg. Value Depr. Col. 12 3 4 5 6 3 7 % Current Value Minus Depr. Garage—Class Z Depr. 2% 3% Carport—Factor Cars L Floor Walls Avg. Roof Record Schools Carport Schools Walls Avg. Roof Roof Doors Walls Avg. Carport—Factor Cars L Floor Walls Avg. Carport—Factor Cars L Floor Walls Avg. Roof Roof Doors			/		70	\dashv	43
Class Tub Trays Basin 1 Sink 1 Toiled 1 Wtr. Sftr. Shr. Str. O.T. Dishwasher Garbage Disp. Built-in-Appliances Heat—Stove H.A. Steam Stkr. Blr. 209 Oil Gas Coal Pipeless Radiant Air Cond. Finish—Fir Hd. Wd. Other Cabinets Mantels Tile — Walls Wainseot Floors Storm Sash—Wood D. S. ; Metal D. S. Total Additions Year Built Avg. Current Value Scommission Adj. % Neighbor - Record - Est. Current Value Minus Depr. \$ 1313 Garage — Class Z Depr. 2% 3% Carport — Factor Cars — Floor Roof R Doors Total Additions Walls Avg. Carport — Factor Cars — Floor Str. Cost Remodel Roof R Doors		/	/	-	NTV	\dashv	47
Plumbing Wtr. Sftr. Shr. Str. Str. O.T. Dishwasher Garbage Disp. Built-in-Appliances Heat—Stove H.A. Steam Stkr. Blr. Oil Gas Coal Pipeless Radiant Air Cond. Finish—Fir Hd. Wd. Cabinets Mantels Tile - Walls Wainseot Floors Storm Sash—Wood D. S. ; Metal D. S. Total Additions Year Built Avg. Current Value Commission Adj. Inf. by Owner - Tenant Bldg. Value Depr. Col. 12 3 4 5 6 3 7 % Remodel Year 1956 Est. Cost Garage—Class Depr. 2% 3% Carport—Factor Cars Floor Radiant Walls Mantels Total Additions Year Built Avg. Current Value Commission Adj. % Current Value Depr. Col. 12 3 4 5 6 3 7 % Carport—Factor Cars Floor Avg. Scarport—Factor Cars Floor Avg. Walls Mantels Doors Walls Mantels Total Additions Year Built Avg. Carport—Factor Cars Floor Avg. Scarport—Factor Cars Floor Avg. Scarport—Factor Carport Walls Mantels Doors		/	1			1	2
Plumbing Wtr. Sftr Skr. St O.T Dishwasher Garbage Disp. Built-in-Appliances Built-in-Appliances Built-in-Appliances Stkr Blr 209 Oil Gas Coal Pipeless Radiant Air Cond. Finish Fir Hd. Wd Other Hd. Wd Other Floors Storm Sash Wood D S; Metal D S Storm Sash Wood D S; Metal D S Storm Sash Wood D S; Metal D S Storm Sash Wood D S S		-					,,
Dishwasher Garbage Disp. Built-in-Appliances Heat—Stove H.A. Steam Stkr. Blr. 209 Oil Gas Coal Pipeless Radiant Air Cond. Finish—Fir Hd. Wd. Other Cabinets Mantels Tile — Walls Wainseot Floors Storm Sash— Wood D. S. ; Metal D. S. Total Additions Year Built Avg. Current Value \$ \$550 Age Commission Adj. % Bidg. Value Depr. Col. 12 3 4 5 6 3 7 % Current Value Minus Depr. Garage — Class — Depr. 2% 3% Carport — Factor Cars — Floord Walls Avg. Roof R Doors Walls Avg. Carport — Factor Cars — Floord Walls Avg. Roof R Doors Walls Avg. Carport — Factor Cars — Floord Walls Avg. Roof R Doors	Plumbing	1					3
Heat—Stove H.A. Steam Stkr. Blr. 209 Oil Gas Coal Pipeless Radiant Air Cond. Finish—Fir Hd. Wd. Other Cabinets Mantels Tile — Walls Wainseot Floors Storm Sash—Wood D. S. ; Metal D. S. Total Additions Year Built Avg. Current Value Age Commission Adj. % Inf. by Owner - Tenant - Neighbor - Record - Est. Remodel Year 156 Est. Cost Current Value Minus Depr. Garage — Class Z Depr. 2% 3% Carport — Factor Cars L Floorwing Malls And Roof Record - Est. Total Additions Value Depr. 2% 3% Carport — Factor Cars L Floorwing Malls And Roof Record - Est. Total Additions T		- 1			410		5
Oil Gas Coal Pipeless Radiant Air Cond. Finish—Fir Hd. Wd. Cabinets Mantels Tile - Walls Wainseot Floors Storm Sash— Wood D. S. ; Metal D. S. Total Additions Year Built Avg. Neighbor - Tenant - Neighbor - Record - Est. Remodel Year Storm Sash— Current Value Depr. Col. 12 3 4 5 6 3 7 % Current Value Minus Depr. Garage — Class Z—Depr. 2% 3% Carport — Factor Cars — Floorly Walls And Roof Roof Record Poors Walls And Roof Roof Record Depr. Section Record Roof Roof Record Record Roof Record Roof Record Roof Record Record Record Record Record Record Record R	Built-in-Appliances					1	1
Air Cond. Finish—Fir					209		3
Air Cond. Finish—Fir	Oil Gas _ Coal	Pipel	essR	adiant	197	1	3
Floor—Fir	1				\	4	3
Cabinets Mantels Tile - Walls Wainseot Floors Floors Storm Sash - Wood D S; Metal D S Storm Sash - Wood D S; Metal D S Storm Sash - Wood D S; Metal D S Storm Sash - Wood D S; Metal D S Storm Sash - Wood D S; Metal D S Storm Sash - Wood D	Finish— FirAd.	Wd	GAA	2			2
Total Additions Year Built Avg. Current Value Age Commission Adj. % Inf. by Owner - Tenant - Neighbor - Record - Est. Remodel Year 1956 Est. Cost Current Value Minus Depr. Garage - Class Z Depr. 2% 3% Carport - Factor Cars Floorly Walls And Roof R Doors	Floor— Fir Hd. W	Vd	Other_	the		4	R
Storm Sash—Wood D S; Metal D S Total Additions Year Built Avg Current Value	CabinetsMante	ls				-	de
Total Additions Year Built	Tile - WallsWair	nseot	Floors			4	à
Year Built Avg. Age Current Value \$ \$550 Inf. by Owner - Tenant - Bldg. Value Depr. Col. 12 3 4 5 6 3 % Remodel Year 956 Est. Cost Current Value Minus Depr. \$ 1313 Garage - Class Z Depr. 2% 3% Carport - Factor Cars Floorly Walls And Roof Re Doors	Storm Sash— Wood D	S;	Metal D	_ s			00
Year Built Avg. Age Current Value \$ \$550 Inf. by Owner - Tenant - Bldg. Value Depr. Col. 12 3 4 5 6 3 % Remodel Year 956 Est. Cost Current Value Minus Depr. \$ 1313 Garage - Class Z Depr. 2% 3% Carport - Factor Cars Floorly Walls And Roof Re Doors							B
Year Built Avg. Age Current Value \$ \$550 Inf. by Owner - Tenant - Bldg. Value Depr. Col. 12 3 4 5 6 3 % Remodel Year 956 Est. Cost Current Value Minus Depr. \$ 1313 Garage - Class Z Depr. 2% 3% Carport - Factor Cars Floorly Walls And Roof Re Doors						1	
Age Commission Adj. % Inf. by Owner - Tenant - Neighbor - Record - Est. Remodel Year 956 Est. Cost Current Value Minus Depr. \$ 1313 Garage - Class Z Depr. 2% 3% Carport - Factor Cars Floondart Walls And Roof Re Doors	Total Additions	19			1206		\
Inf. by Owner - Tenant - Neighbor - Record - Est. Remodel Year 1956 Est. Cost Garage - Class Z Depr. 2% 3% Carport - Factor Cars Floordust Walls Roof	Year Built Avg	. 60	Current V	alue		\$	8550
Remodel Year 956 Est. Cost Current Value Minus Depr. \$ 1313 Garage - Class Z Depr. 2% 3% Carport - Factor Cars Floodut Walls And Roof R Doors		50			%		
Remodel Year 1956 Est. Cost Current Value Minus Depr. \$ 1313 Garage - Class Z Depr. 2% 3% Carport - Factor Cars I Floodut Walls And Roof R Doors		- Est.				-	
Garage - Class Z Depr. 2% 3% Carport - Factor	alt			9		#	1212
Cars Floordest Walls And Roof RR Doors						1	1313
Size 17 x 71 Account weed materials 205 79x							
Dize I Age Well I Cost	Size - 12 x 21 Age	954 mae	Cost	205	x 79 %		162
Other				× 4	_ ^ 70		100
Total Building Value \$			Tot	al Building	Value	8	
Appropried 10-24 1057: pt 1331	10-20		= -			H *	



KIND OF BUILDING	61	61	61	61	61	61	61	61	61	61
GARAGE										
RESIDENCE							55			
TOTAL										
ASSESSED	To the second									*
KIND OF BUILDING	8561	55.61	0961	1961	2961	61	61	61	61	- 61
GARAGE	951	150	143	137	131					
RESIDENCE	8121	2421	1207	1 [] 1	1136					
TOTAL	1434	1392	1350	1308	1267					
ASSESSED VALUE	515	525	540	525	505					

Location Kind of Bldg					
Kind of Bldg	4			SP	A C;
	Res	St.	No. 44	1 -	
Class 4		_ Туре 1⁄2 3 4		1 at	KAUC
Stories Dime	ensions	Sq. Ft.	Factor	I	X
x	x	832	Factor	Totals	Т
x	x	072		s 4438	\$
x	x	1 1 1			
Att. Gar.—C.P		la XV II			
	Description o	lr Walls_	Cl	_	
				Additions	Addit
Foundation—Stone Ext. Walls 5/	e /	Conc.	_Sills		
Poof Tune	<u> </u>		1)		
Roof Type GA	D	_ Mtl. /a7	-		
Dormors—Small	Med.	- Large			
Bays_Small			DORM	ER 160	
Porches—Front		1604	@ 200	320	
Rear			_@		
Porch			. @		120
Planters			@		
Ext. Base. Entry	10		@		
Cellar-Bsmt. — 1/4	1/8 1/2 1/8 3/4	Full Flo	or	80	
Bsmt. Gar					
Basement-Apt.	Rms	Fin. Rms			
Attic Rooms Fin.	2	TT-6:		525	
/ Class	T	ıb Tr	ave	F	
Plumbing Basin	Sinl	kToile	t /	1550	
Plumbing Class Basin Wtr. S.	ftr S	Shr. St	О.Т		
Distiwa	isher	Garbage Die	m		
Heat—Stove H.A.	FA	HW Stkr_	Elec.		
Oil Gas X_	Coal Pi	peless Pad	lant	347	
Air Cond. — Full _	2017	Zono			
Finish—Fir.	Hd. Wd	Panel .			
Floor-Fir_	Hd. Wd	Other			
Cabinets/	Mantels	A CONTRACTOR OF THE PARTY OF TH			
Tile -Walls	_Wainscot_	Floor	g		
Storm Sash—Wood I	o s	: Metal D.	g		
Awnings — Metal _		Fiberglass			
130-41					
Total Additions				1000	
Year Built 1907	Aug 1/2			178	
10/11	536			6420	
90	Age 2.	Obsolescence			
nf. by Neighbor R	ecord - Est	Adj. Bld. Va	lue		
, ,		Conv. Factor		x.47	
		Cost-1940 Ba			
	A	Column 12 3	4 5 6		
D	epreciation	2 3			
D	940 Base Cos	t, Less Deprecia	ition		
D	940 Base Cos	t, Less Deprecia	ition	227	
D	940 Base Cos se side	t, Less Deprecia	value \$	237	



OVER PULLDINGS	Age	Size	Area	Fac- tor	Cost	Conv. Fac.	Adj. Cost	Value
RESIDENTIAL OUT BUILDINGS		x				.47		
						.47		
		x				.47		
		x				.47		
	7411	x		1	1	.47	2	
		x	-	45	1	.47		
		x				1 .41		
1940 Base Cost	x 5	Cost 2	or	Data1	ation	1:		
REMARKS Average Year	of Co	onstruct	- 58	Ve	ar =		551	0
Veer 1907 \$ 6073 =	=Z.	2 % 2		Y	-		0	5
10/1/ 24/		7/0				-	551	3
Average Year of Co	onstru	iction	anhands doors	200000		_	58	5 25
TC-74 REV. 61 STATE OF UTAH - STATE TAX CO	MMISSI	ON	-2		,			



Utah State Historical Society

Historic Preservation Research Office

Site No.	

Structure/Site Information Form

1	
DEN.	

Street Address: 445 Park UTM: 12 458070 4499100

Park City, Summit County, Utah
Name of Structure: Milton and Minerva Thomas House T. R. S.

Present Owner: Greg N. and Nancy G. Orrell

Owner Address: 1236 9th Street #2, Santa Monica, CA 90401

Year Built (Tax Record): Effective Age: Tax #: PC 58
Legal Description Kind of Building:

Lots 12 & 13, Block 4, Park City Survey.

Less than one acre.

2	Original Owner: probably Milton & Minerva Thomas			Construction Date: c. 1880 Demolition Date:					
S/US	Original Use:	Residence		Present Use:					
STATUS/USE	Building Condi	ition:	Integrity:	Preliminary Eva	luation:	Final Register S	tatus:		
	Excellent	□ Site	☐ Unaltered	☐─Significant	□ Not of the	☐ National Landmark	□ District		
	□ Good	☐ Ruins	☐ Minor Alterations	□ Contributory	Historic Period	☐ National Register	☐ Multi-Resource		
	☐ Deteriorated		⊞ Major Alterations	☐ Not Contributory		☐ State Register	☐ Thematic		
3	Photography:	Date of S	Slides: 1983	Slide No.:	Date of Photo	graphs: 1983	Photo No.:		
	Views: ☐ Front ☐ Side ☐ Rear ☐ Other		Vie	ews: 🗆 Front 🗆 Side	□ Rear □ Other	_			
DOCUMENTATION	Research Sources:								
ΗĀ	Abstract of Title	☐ Sanbo	orn Maps	Newspapers		☐ U of U Library			
Ē	☐ Plat Records / Ma	p 🗆 City 🛭	Pirectories	☐ Utah State Histo	rical Society	☐ BYU Library			
Š	d-∓ax Card & Photo	□ Biogra	aphical Encyclopedias	☐ Personal Intervi	ews	☐ USU Library			
ŏ	 Building Permit 	₫_Obi tu	rary Index	 LDS Church Arc 	hives	☐ SLC Library			
	□ Sewer Permit	☑_Coun	ty & City Histories	☐ LDS Genealogic	cal Society	Other Census I	Records		

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):

1880 Census Records. Summit County, Park City Precinct, pp. 4, 13.

1900 Census Records. Summit County, Park City Precinct.

Researcher:

Roger Roper

Date: 4/84

Site No:

Architect/Builder:

Unknown

Building Materials:

Wood

Building Type/Style:

Hall & Parlor House

Description of physical appearance & significant architectural features:

(Include additions, alterations, ancillary structures, and landscaping if applicable)

This house is a one and one half story frame hall and parlor house with a gable roof. It is set on a raised stone foundation. The arrangement of openings on the facade is atypical, compared with other examples of this vernacular type. The facades of hall and parlor houses are generally symmetrical with a door centered between windows. The openings of this facade, however, are arranged with two windows on one side of the door and a single window on the other. The asymmetrical arrangement of openings corresponds with the internal division of the floor plan. The two rooms at the front of the house are of unequal size. It is likely that there were originally two rooms of identical size at the back of the house, but that space has been altered to include two small rooms and one large room. The size of the front door has been reduced, but that change is minor. A front porch, which was formed by an extension of the roof edge, spans the facade. It is supported on square columns and has a straight post balustrade. A monumental dormer projects from the roof. Styling of the dormer and evidence of the dormer in an old photograph of the area indicate that it was an াল াn-period addition. It has a gable roof and drop siding that matches the siding of the original building. Fishscale shingles highlight the gable. shed roof porch attached to the front of the dormer has square posts and a (See continuation sheet)

Statement of Historical Significance:

Construction Date: c. 1880

Built c. 1880, the Milton and Minerva Thomas House at 445 Park is architecturally significant as one of 76 extant hall and parlor houses in Park City, 22 of which are included in this nomination. The hall and parlor house, the earliest house type to be built in Park City, and one of the three most common house types that were built during the early period of Park City's mining boom era, significantly contributes to the character of the residential area.

This house was built by at least 1889, as indicated by the Sanborn Insurance Maps, having probably been built in the late 1870s by Milton and Minerva Thomas. Although the Thomases did not receive legal title to the property until 1882, it was not unusual during the early decades of Park City's settlement for individuals to build their houses on land which they had obtained through informal rather than legal transactions. 1880 census records indicate that the Thomases were living in this neighborhood at that time, so it is possible that this house was built and being used by them before 1880. Milton was a native of Texas (b. c.1849) and a miner, and Minerva was a Utah native (b. 1860). They had at least two children while living in this house.

The Thomases sold this house in 1884 to Thomas and Rebecca Cupid, who lived here for only one year. Thomas served for many years as a U.S. deputy sheriff in Park City. Henry Newell bought this house in 1885 and owned it until 1897. His relatively long length of residence apparently prompted townsfolk to refer to this as the "Newell residence." Henry was a butcher from New York. It was under Newell's ownership, perhaps, that the large dormer was added to the roof of the house.

(See continuation sheet)

STORY **2**


445 Park Description continued:

straight post balustrade. The porch is probably a more recent addition than the dormer itself. Every effort was made, however, to create a structure that complements the original building. This house, with the addition of the dormer, reflects a common method of expansion of a simple rectangular house. The top half story of the building was opened up by adding a dormer. In this case, the addition of the dormer is particularly sympathetic with and complementary to the design of the original house. No other major changes are reflected on the exterior of the building, therefore it retains its original character.

History continued:

Other owners of the house include Alfred Thompson (1897-1901), who apparently rented it out, 2 Mathias Jurgensen (1901-05), M.D. Hurlburt (1905-20), and Julius Olsen and family (1920-38).

Park Record, August 25, 1900, p. 3. See 364 Park structure/site form. 2 Ibid.



Marian Carlos Comments



