HISTORIC SITE FORM - HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION							
Name of Property:							
Address: 819 Park Ave		AKA:	AKA:				
City, County: Park City, Summi	t County, Utah	Tax N	lumber: SA-9				
Current Owner Name: WHALE	Y RONALD & REIF ME	ELANIE H/W (JT) F	Parent Parcel(s):				
Current Owner Address: PO BOX 1621 PARK CITY, UT 84060-1621							
Legal Description (include acreage) BEG AT A PT 43.35 FT N 28*50' W FROM THE SE COR OF LOT 4 BLK 2 SNYDERS ADDITION TO PARK CITY UTAH & RUN TH N 28*50' W 43.35 FT TO A PT ON THE E'LY LINE OF SD BLK 2; TH SW'LY TO A PT ON THE W'LY LINE OF SD BLK 2 WH IS 78 FT N 31*48' W FROM THE SW COR OF SD LOT 4; TH S 31*48' E 39 FT TO A PT ON THE W'LY LINE OF SD BLK 2 WH IS 39 FT N 31*48' W FROM THE SW COR OF SD LOT 4; TH NE'LY IN A STRAIGHT LINE 139 FT M/L TO THE PT OF BEG & BEING A PART OF LOTS 4 & 5 OF SD BLK 2 SNYDERS ADDITION TO PARK CITY UTAH CONT; Acres 0.13							
2 STATUS/USE							
Property Category ☑ building(s), main ☐ building(s), attached ☐ building(s), detached ☐ building(s), public ☐ building(s), accessory ☐ structure(s)	Evaluation* □ Landmark Site □ Significant Site □ Not Historic *National Register of □ listed (date:)	Reconstruction Date: Permit #: □ Full □ Partial Historic Places: ☑ in	<u>Use</u> Original Use: Residential Current Use: Residential eligible □ eligible				
3 DOCUMENTATION							
Photos: Dates ☑ tax photo: ☑ prints: 1995 & 2006 □ historic: c. Drawings and Plans □ measured floor plans □ site sketch map □ Historic American Bldg. Surv. □ original plans: □ other:	□ abstract o □ tax card □ original bu □ sewer per □ Sanborn N □ obituary ir □ city director vey □ census re □ biographic □ newspape	f title uilding permit mit Maps ndex ories/gazetteers cords cal encyclopedias ers	ces consulted, whether useful or not) city/county histories personal interviews Utah Hist. Research Center USHS Preservation Files USHS Architects File LDS Family History Library Park City Hist. Soc/Museum university library(ies): other:				
 Bibliographical References (books, articles, interviews, etc.) Attach copies of all research notes and materials. Blaes, Dina & Beatrice Lufkin. "Final Report." Park City Historic Building Inventory. Salt Lake City: 2007. Carter, Thomas and Goss, Peter. Utah's Historic Architecture, 1847-1940: a Guide. Salt Lake City, Utah: University of Utah Graduate School of Architecture and Utah State Historical Society, 1991. McAlester, Virginia and Lee. A Field Guide to American Houses. New York: Alfred A. Knopf, 1998. Roberts, Allen. "Final Report." Park City Reconnaissance Level Survey. Salt Lake City: 1995. Roper, Roger & Deborah Randall. "Residences of Mining Boom Era, Park City - Thematic Nomination." National Register of Historic Places Inventory, Nomination Form. 1984. 4 ARCHITECTURAL DESCRIPTION & INTEGRITY 							

Researcher/Organization: Dina Blaes/Park City Municipal Corporation Date: November, 08

Building Type and/or Style: Other building type	No. Stories: 1 ½								
Additions: ☐ none ☑ minor ☐ major (describe below) Alterations: ☐ none ☑ mino	r □ major (describe below)								
Number of associated outbuildings and/or structures: \square accessory building(s), #	; structure(s), #								
General Condition of Exterior Materials:									
☑ Good (Well maintained with no serious problems apparent.)									
☐ Fair (Some problems are apparent. Describe the problems.):	☐ Fair (Some problems are apparent. Describe the problems.):								
☐ Poor (Major problems are apparent and constitute an imminent threat. Describe the problems.):									
□ Uninhabitable/Ruin									
Materials (The physical elements that were combined or deposited during a particular period of time in a particular pattern or configuration. Describe the materials.): Foundation: Not visible and therefore its materials cannot be verified.									
Walls: Wood ship-lap siding.									
Roof: Unable to determine based on angle of 2006 photo- 1995 photo exhibits	s wood shingles.								
Windows/Doors: Double hung with wood frames, and some aluminum sliding v 4 small panels of glazing above 3 horizontal panels on a wooden door.	vindows. Visible doors show								
Improvements: TOOL SHED; 48 SF; Quality-TYPICAL & TOOL SHED; 96 SF;	Quality-TYPICAL								
Essential Historical Form: ☑ Retains ☐ Does Not Retain, due to:									
Location: ☑ Original Location ☐ Moved (date) Original Location:									
Design (The combination of physical elements that create the form plan space structure and style [Secribe additions and/or alterations								

Design (The combination of physical elements that create the form, plan, space, structure, and style. Describe additions and/or alterations from the original design, including dates--known or estimated--when alterations were made): A very unique design incompatible with housing types commonly found throughout this timeframe, and yet still reflective of the later era of mining town residential construction in scale and elements of style. Building card estimates the construction date around 1941, with slight material adjustments made over time (as seen in the change of window materials from large picture windows with rectangular muntins, to pairs of double hung windows in 1995 photo). Siding materials appear to change by the 1995 photo, as does the appearance of a new upper storey sliding window facing the street. Possible evidence of a later rear addition seen in 1995 photo (behind rear property fence) where roofing materials change in tonal color. Form of structure has overall been left intact.

Setting (The physical environment--natural or manmade--of a historic site. Describe the setting and how it has changed over time.): Narrow building lot on fairly flat terrain. House is recessed roughly 5-10 feet from the city roadway, and building lot appears to sink down from roadway by several inches. Neighboring property type to the right of the front elevation is not consistent with historic context of property in question. Little to no landscaping visible from provided photos.

Workmanship (The physical evidence of the crafts of a particular culture or people during a given period in history. Describe the distinctive elements.): The distinctive elements that define the typical Park City post-mining era home are simple forms (rectangle or central block cottage), the use of wood siding, the simple roof form (broader and lower pitched than the mining era), the informal landscaping, the restrained ornamentation, and the plain finishes.

Feeling (Describe the property's historic character.): The physical elements of the site, in combination, convey a sense of life in the post-mining era of Park City.

Association (Describe the link between the important historic era or person and the property.): This unique housing type, while not compatible with commonly recognizable structural forms of this era, lends a similar scale, building approach, and sentiment concurrent with other housing types during the mining era of Park City.

This site, while it retains its essential historical form, does not meet the criteria for listing in the National Register of Historic Places.

5 SIGNIFICANCE		
Architect: ☑ Not Known ☐ Known:	(source:)	Date of Construction: c. 1942 ¹
Builder: ☑ Not Known ☐ Known:	(source:)	
The site must represent an important significant under one of the three are	part of the history or architecture of the cor as listed below:	mmunity. A site need only be
 Historic Era: □ Settlement & Mining Boom Era □ Mature Mining Era (1894-1930) ☑ Mining Decline & Emergence of 	,	
•	of the top three metal mining districts in the the three thr	S S

boom period of the late nineteenth and early twentieth centuries. However, by the mid-twentieth century, most mines in Park City had closed, the population had dwindled, and building activity nearly ceased. Though the few houses built during this period generally reflect the types and styles used in communities throughout Utah, they were constructed in a way that reinforces the settlement patterns of Park City's significant mining era. They are both modest in scale and tightly packed, even on the hillsides, contributing to the overall character of the community.

- 2. Persons (Describe how the site is associated with the lives of persons who were of historic importance to the community or those who were significant in the history of the state, region, or nation):
- 3. Architecture (Describe how the site exemplifies noteworthy methods of construction, materials or craftsmanship used during the historic period or is the work of a master craftsman or notable architect):

6 PHOTOS

Digital color photographs are on file with the Planning Department, Park City Municipal Corp.


Photo No. 1: East elevation (primary façade). Camera facing west, 2006.

Photo No. 2: Southeast oblique. Camera facing northwest, 1995.

Photo No. 3: East elevation (primary façade). Camera facing west, tax photo.


 $^{^{\}rm 1}$ Utah State Historical Society, Structure/Site Form, 1978 and Summit County Recorder.

SERIAL NO. X 2.80 RE-APPRAISAL CARD (1940 APPR. BASE) Owner's Name Owner's Address. Location Z Kind of Building. Class Schedule Type 123-4 Cost \$ Stories Dimensions Totals Cu. Ft. Sq. Ft. Factor 1419 x No. of Rooms_ Condition Description of Building Add Deduct Foundation-Stone Ext. Walls 5 Insulated-Floors. Roof-Type__ Dormers-Small Bays-Small Med. Porches-Front 40 Cellar-Basm't--14 1/2 1/2 3/4 full-floor Basement Apts .- Rooms Fin. Attic Rooms_ Unfin. Class Tub Tra
Basin / Sink / Toile
Urls Ftns Shr
Dishwasher Garbage Disp. Trays. Sink___Toilet. Plumbing-410 Shr. Heat—Stove H. A. Steam S. Coal Air Conditioned Incinerators. Radiant-Pipeless. Finish 40 Cabinets Mantels Lighting-Lamp. Total Additions and Deductions_ Net Additions or Deductions. REPRODUCTION VALUE Owner Tenant Neighbors Records Ave Age Zyrs. by Depr. 12-3-4-5-6_ Reproduction Val. Minus Depr. Remodeled 1945 Est. Cost Remodeling Inc. Garage S 8___ C__ Depr. 2% 8% Obsolescence. _Walls_ Cars. Out Bldgs. Roof_ Floor_ Depreciated Value Garage Remarks. Total Building Value 2 3 194 9 By_ Appraised.




OUT BUILDINGS	Age	Size	Area	Fac- tor	Cost	Depr. Value
3		x	(
		x	11	1	/	
		x		10/1	2.3	
		х	1	10		
		x		h	=-	
\n\		x	/			
		/x /	1		/	
1, 2/2	0	/ x /	1	1	1	
7-10		V x/			11	
() ()	1	/x /		1	15	
		//x			7	
1/h		/ 'V _x)	1		•	1
V 10	1	x	7 K			1.
1	-	x	*	//	,	_
70		х	1	/	-	-
	1.	X	1/	0	- 4	1

# CER	21 ,		0114			
Locatio	n Block	2 0H	PHADTS	4+5-	77 1 2	
Kind of	Bldg.	1	St. No.	-	rark a	
Class	. 3	14)	Туре 1 2 🕄 4. (Cost \$	376	X 100 %
Stories	Dimensi	ons	Cu. Ft.	Sq. Ft.	Factor	Totals
1	x	x		1419		\$ 2376
	x	x	+			2070
	x	x				· · · · · · · · · · · · · · · · · · ·
Gar.—C	arport >	Flr.	Walls _	Cl		
	Desc	ription of	Buildings		Additions	
Foundat	ion—Stone	Co	nc1	None V		
	40		on Sid	L. Charles and L.		
Insulati	on—Floors	Walls	Clgs	20		
	pe Gabi			a		
			Large	-		
			Large			
			98 0	and the same of th	78	
				1		
17 Table 10			@	/		
			Mtl. Rail			
	nt Entr.		<u> </u>	./		
		-				
	Service Control of	1/, 2/, 3/, Fu	ıll Floor_			
		222	Unfin,	/		
	oms Fin.		/			
Attie Ro			Tray			
	Basin	/ Sink	Toile	t /		
Plumbin			hr. St.			
	Dishwash	er	Garbage Disp		410	
Built-in-	Appliances _	_				
Heat-S	tove H.A	Stear	n Stkr	Blr.		
Oil	_Gas	Coal1	PipelessR	adiant		
Air Cone	i.					11
Finish-	Fir	_Hd. Wd.				
Floor-	Fir	Hd. Wd/_	Other .			
	1					-8
Tile – W	alls	_Wainseot	Floor			5 12
		/	=; Metal D. 7	7)		M
			2400		240	1
Total Ad	ditions	/			728	728
Year Bu	ilt/	Avg. /6	Current V	alue		8 3104.
VEage	1940	Age .	Commission	n Adj.	%	1411 - 17
Inf. by	Neighbor - I	lant - Record - Est		. Value	7,	11
Remodel		stCost	Depr. Col.	1 2 3 4 5 6		. 77
			% 3% Carport	alue Minus I	epr.	\$ 2204
			% 3% Carport	. 1	- 11	
		V		1	- 11	
Other _		-\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Cost		x %	
Julei			m.	al D. III		
		***		al Building V		\$
	. 4	- 13 -		120	1 "	



OF Card Number

Owners	Nama							-	
Location	*	- 1	ARI	K	CIT	- 4			
Kind of	A	Per	_		No.819	7	Park	. ,	Alie
Class	4		Typ	e 1 2/3/4			-		v/000
Stories	Dimensi	ons		1. Ft.	Factor		Totals	T	Totals
/			_		4169			-	Totals
	x	x	10	03	7-	\$ (0///	\$	
	x	x							
Att Gar	x .—C.P	x 1	elr.	_ Walls_	Cl		'		
Titti Gui		cription			01		Additions		Additions
73 . 1 . 1			529		G'II.				
	ion—Stone	SPHA	Conc.	fk	_Silla_				
Ext. Wa	pe ga	11 0	Mtl	1	1 X	-			
	_Small								
Dave C	mell	Mod		Large		-//			
Porches-	-Front	. meu _		119	@35	-0	357		
Rear	Front			240	38	-	720		
					193				
	e. Entry								
	smt. — 1/4 1/3								
	ır								
Basemen	t-Apt	_ Rms.		Fin. Rn	ns				
Attic Ro	oms Fin			Unfin					
	/ Class _	2	Tub		Trays		1 .~~	Н	
2270 (17)	Basin _	_/_ s	Sink_		oilet/		650		
Plumbin	Wtr. SI	tr	_ Snr.	St	_ 0.1				
	Dishwas	sher		Garbage	Disp			Н	
Heat—St	ove H.A.	FA 1	HW	Stkr	Elec	-	451		
Oil	_ Gas	Coal	Pipele	ess F	Radiant	-		H	
	. — Full _					-		\vdash	
Finish—l	Fir I	Hd. Wd.	-	Par	nel	-		H	
	ir				er				
						\dashv		\vdash	
Tile -Wa	ılls	_Wains	cot	CL. 2F	loors	5	71-		
Storm Sa	ash—Wood I	DS.	;	Metal D.		-	265		
Awnings	— Metal _		F	iberglass		-	100	\vdash	
						-			The same
						_			
			7.19			-	7/1/1/5	H	
Total Ad	10111					-	XYYJ	\vdash	
Year Bu	ilt. 1947	Avg. 1		Replacer	ment Cost	-	8554		
		Age 2	2.	Obsoles	ence	_	/		
Inf. by	Owner Te		F-t	Adj. Blo	l. Value	_		\sqcup	
	Neighbor -	necord -	Est.	Conv. Fa	actor		x.47		
		Replace	ment (Cost—194	Base	_			
	2	Depreci	ation (Column 1	2345	6			
		1940 Ba	se Cost	, Less De	preciation			\square	
Total Va	lue from reve	erse side				_			
	-		Т	otal Buil	ding Valu	ie	\$		1069
Appraise	d ①/C	2-17		19.6	By /	51	NOV 2	9	1300
Appraise				19		, i	70		



			tor		Fac.	Cost	Value
	x				.47		
	x				.47	7	
	x				.47		
	x	1	-	1	.47		
ur J	x				.47	-	
	x				.47		
x	_ Cost % Depr			. x 47 9	76		
	ls x	x x x x x x 3% Ro Cost x % Depr	x x x x x x x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x	X	X

TC-74 REV. 61 STATE OF UTAH - STATE TAX COMMISSION



Researcher: Date:

Philip F. Notarianni September,1978 dednt inte

Site No. SU-10-590

Utah State Historical Society Historic Preservation Research Office Structure/Site Information Form

				The state of the s	CRESCO TAMORISMO CONTRACTOR		parameter and a love transfer experience	rangelly report
IDENTIFICATION ************************************	Street Address: Name of Structure:	819 Park Ave.				Plat _{SA} B T. R.	I. 2 Lot SE S.	_4
FILE	Present Owner:	Edwin S. Ehlers a	nd Ronald R. I	Whale		UTM:		_
OE	Owner Address:	P.O. Box 1601, Pa	rk City, Utah	84060		Tax #:	SA-9	
2	Original Owner:		Constructio	n Date:	1942	Demolition	Date:	_
	Original Use:	residential						
AGE/CONDITION/USE	Present Use: Mainti-Family Dublic Commercial	□ Park □ Industrial □ Agricultural	□ Vacant □ Religious □ Other			Occupa	nts:	
	Building Condition: Excellent Good Deteriorated	□ Site □ Ruins	Integrity: Unaltered Minor Alterati Major Alterati					manh libera
STATUS	Preliminary Evaluatio Significant Contributory Not Contributory Intrusion	n:		Final Reg National La National Re State Regis	indmark E			en and a second
DOCUMENTATION	Photography: Date of Slides: 7/78 Views: Front ✓ Side □ Rea	ar □ Other □		Photographs: ront Side C	□ Rear □ (Other 🗆		
	Research Sources: Abstract of Title Plat Records Plat Map Tax Card & Photo Building Permit Sewer Permit Sanborn Maps	☐ City Directories ☐ Biographical Encycl ☐ Obituary Index ☐ County & City Histor ☐ Personal Interviews ☐ Newspapers ☐ Utah State Historica	ries		orary orary			

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):

Summit County Records.

0	ú
ι	
i	r
:)
į	5
L	L
ŀ	=
;	Ĺ
	۲
0	ĭ

「自動器の、他」からはないこと、しょうことのよう。他となるとうとは必要し、これはないなど、自動をできているからいいがない。これではこのななるとはころうない。	《李明·李明·李明·李明·李明·李明·李明·李明·李明·李明·李明·李明·李明·李
Architect/Builder:	The state of the s
Building Materials: wo	Building Type/Style:
Description of physical	ppearance & significant architectural features:

(Include additions, alterations, ancillary structures, and landscaping if applicable)

6	Statement of Historica	I Significance:		Control of the Contro
HISTORY.	☐ Aboriginal Americans ☐ Agriculture ☐ Architecture ☐ The Arts ☐ Commerce	□ Communication □ Conservation □ Education □ Exploration/Settlement □ Industry	☐ Military ☐ Mining ☐ Minority Groups ☐ Political ☐ Recreation	☐ Religion☐ Science☐ Socio-Humanitarian☐ Transportation

While the structure is sympathetic in vernacular style and treatment, its age renders it non-contributory to the Park City Residential Historic District.



