HISTORIC SITE FORM – HISTORIC SITES INVENTORY

PARK CITY MUNICIPAL CORPORATION (10-08)

1 IDENTIFICATION			
Name of Property: House at 569	Park Avenue		
Address: 569 Park Avenue			A.K.A.:
City, County: Park City, Summit	County, Utah		Tax Number. PC-82
Current Owner Name: William A	. and Janet Kershaw,	, et. al.	Parent Parcel(s): N/A
Current Owner Address: 620 My	rstic Lane, Sacramen	to, CA 95864	
Legal Description (include acrea legal description)	<i>ge)</i> : LOTS 17 & 18 B	LK 5 PARK CITY SURVE	EY [] (see record for complete
2 STATUS/USE			
 □ building(s), main □ building(s), attached □ building(s), detached □ building(s), public 	Evaluation* Landmark Site Significant Site Not Historic National Register of listed (date:)	Reconstruction Date: Permit #. □ Full □ Partial Historic Places: □ eligibl	Use Original Use: single dwelling Current Use: single dwelling e ⊠ ineligible
3 DOCUMENTATION			
Photos: Dates		title [Iding permit	city/county histories city/county histories personal interviews Utah Hist. Research Center USHS preservation files USHS architects file LDS Family History Library Park City Hist. Soc./Museum university library(ies): other:
Studies, Graduate School of A Hampshire, David, Martha Sonn Summit County Commission,1 National Register of Historic Place #79002511. Peterson, Marie Ross and Mary City: Daughters of Utah Pioned Randall, Deborah Lyn. Park City Arts thesis, University of Utah,	. Utah's Historic Arch trchitecture, Universit tag Bradley and Aller 998. ces. Park City Main S M. Pearson. Echoes ers, 1947. r, Utah: An Architectur 1985.	nitecture, 1847-1940. Saliny of Utah and Utah State on Roberts. A History of Subtreet Historic District. Paid of Yesterday: Summit Control History of Mining Tow	t Lake City: Center for Architectural Historical Society, 1988. ummit County. Coalville, UT:

Researcher/Organization: John Ewanowski, CRSA Architecture Date: Nov. 2014

4 ARCHITECTURAL DESCRIPTION AND INTEGRITY

Building Type and/or Style: bungalow type, Victorian Eclectic style	No. Stories: 1
Additions: 🛮 none 🗌 minor 🔲 major (describe below) Alterations: [☐ none ☐ minor ☒ major (describe below)
Number of associated outbuilding and/or structures: accessory building and/or structures:	lding(s), # <u>0</u> ; structure(s), # <u>0</u> .
General Condition of Exterior Materials:	
$oxed{\boxtimes}$ Good: Well-maintained with no serious problems apparent	
☐ Fair: Some problems are apparent. <i>Describe the problems</i> :	
☐ Poor: Major problems are apparent and constitute and imminent	threat. Describe the problems:
☐ Uninhabitable/Ruin	
Materials:	
Foundation: concrete	
Walls: clapboard siding	
Roof: wood shingles	
Windows/Doors: slider windows (typical) and glazed wood front doo	r with wooden trim.
Essential Historical Form: 🛛 retains 🔲 does not retain	
Location: original location moved (date: , original location:)	
Des <i>ign</i> : This bungalow is rectangular in plan, with a full width front por	

Design: This bungalow is rectangular in plan, with a full width front porch and central entrance. The roof structure has been modified from a hipped type to include a gable on the front (east) elevation, a renovation that occurred after a tax photograph taken in the early 1940s. The front porch is made of wood and contains some Victorian-inspired details. Slider windows have been installed to replace the original windows, which were presumably double-hung type.

Setting: Set in Old Town Park City, one block west of historic Main Street. With narrow lots and streets, the neighborhood is relatively dense for single-family zoning. The house is set on a double-wide lot, which is approximately 50'x75'. Many of the surrounding houses are historic.

Workmanship: Was constructed of less common materials than surrounding Victorian residences, including clapboard siding, wood roof shingles, and slider windows, although these materials were also used to a small degree in Park City. Drop wood siding, asphalt shingles, and double-hung windows were more common. Some of the wood trim accents on the front façade suggest the Victorian style, but these were added after the 1940s tax photo and are not original.

Feeling: Retains historic feel through material usage and details, although the original appearance has been altered somewhat. Bungalows were not as common in Park City as rectangular cabins, T-cabins, and pyramid houses, but that has the feel of a historic sample of that type.

Association: The "Mature Mining Era" in Park City, during which the local mines were still producing a large share of the country's silver supply. A decline in silver prices through the 1920s was caused by increased production amidst decreased demand. This drop in prices caught up to Park City mines in the 1930s, which caused a local decline in the industry and an economic downturn, along with the Great Depression. Samuel B. and Alice

Deighton Dunn purchased the property in 1917, immediately taking out an \$800.00 mortgage, suggesting a possible date of construction.¹

5 SIGNIFICANCE
Architect: 🛛 not known 🗌 known: (source:) Date of Construction: c. 1917
Builder: 🖂 not known 🗌 known: (source:)
The site must represent an important part of the history or architecture of the community. A site need only be significant under one of the three areas listed below:
1. Historic Era:
 ☐ Settlement and Mining Boom Era (1868-1893) ☐ Mature Mining Era (1894-1930) ☐ Mining Decline and Emergence of Recreation Industry (1931-1962)
Description of historic era: By the 1890s, Park City was a <i>bona fide</i> mining town, with a railroad station, post office, fire department, and growing school system. While individuals lost and gained jobs based on fluctuating silver prices, the mining industry was relatively stable in Park City through the 1920s. The Great Fire of 1898 proved the strength of the town: while Main Street was almost completely levelled and sustained over \$1,000,000 in damages, most of the buildings were rebuilt by 1900. Unlike other fire ravaged western mining towns, which often went permanently bust over similar blazes, the demand for Park City silver caused a rapid rebuilding of the business district. Park City survived the Spanish Flu Epidemic, World War I, and Prohibition mostly unscathed, boasting over 4,000 residents in the 1930 United States Census.
Persons: Thomas and Matilda Stringer (purchased 1899) and Samuel B. and Alice Deighton Dunn (purchased 1917)
3. Architecture: N/A
5 PHOTOS

Photographs on the following pages (taken by the researcher, unless noted otherwise):

Photo No. 1: Northeast oblique. Camera facing southwest. November 2014.

Photo No. 2: East elevation. Camera facing west. November 2014.

Photo No. 3: Southeast oblique. Camera facing northwest. November 2014.

Photo No. 4: Southeast oblique. Camera facing northwest. Tax photo, c. 1941. (Summit County)

¹ From title abstracts in the Summit County Recorder's Office, Coalville, UT.

Photo No. 1: Northeast oblique. Camera facing southwest. November 2014.



Photo No. 2: East elevation. Camera facing west. November 2014.



Photo No. 3: Southeast oblique. Camera facing northwest. November 2014.





Photo No. 4: Southeast oblique. Camera facing northwest. Tax photo, c. 1941. (Summit County)





569 Park Avenue

Sanborn Map History











EVALUATION FOR HISTORIC POTENTIAL FILES

	(6)	5	2 *		
(enter date :	in blanks)	8		-	
	Preliminary	evaluation H	nade		•
*	Encoded	X			
2/27/86	Added to cou	nty list			e .
	Added to yea	rly record	8		e.
Assoc	TYPE: iated Histori iated Histori iated Histori Builder/Arch Reason for	ic Event ic Theme itect	Significa Significa Significa	ant Style ant Plan/Typ ant Construc ant Material By	tion Type
ALTERED: None		Major Demolished	Reconstr Excavate	ucted	Unknown
Minor	r	Demorran		d ²	
Good		air emolished	Deterior Ruins	ated	Site Unknown
EVALUATION:					
(A) - S	Significant Contributory	Out of Non-co	Period ontributory	No Evaluati	on
160		. relevant i	COMMENTS information to	explain eva	luation)
	(Include an	, , , ,			355
		-		· · · · · · · · · · · · · · · · · · ·	
		*	* * * *		
				(9)	
	5 K 2			(*	
	(8)	iĝa			
	¥0.	7			
				9	
984					24
				50 K	
2 (a)			200		
			Evaluator	•	
			Date:		

Researcher:

Philip F. Notarianni

Date:

August, 1978

Site No. ___SU-10-144

Utah State Historical Society Historic Preservation Research Office

Structure/Site Information Form

1						DI-1	Da Di		. 17 .10
NO.	Street Address:	569 Park Ave.					PC BI.5		17-18
САТ	Name of Structure:					T.	R.	S.	
Ī	Present Owner:	Donald R. Neil et.	al.			UTN	√ 1:		<u> </u>
IDENTIFICATION	Owner Address:	P.O. Box Park Cityk	Utah	84060		Tax	#: I	PC-82	
2	Original Owner:		Constru	uction Date:	@1923	Demo	lition l	Date:	
	Original Use:	residential							
AGE/CONDITION/USE	Present Use: Single-Family Multi-Family Public Commercial	□ Park □ Industrial □ Agricultural	□ Va □ Re □ Ot	ligious		Occ	cupant	S:	
AGE/0	Building Condition: Excellent Good Deteriorated	□ Site □ Ruins		-					
STATUS C	Preliminary Evaluation Significant Contributory Not Contributory Intrusion	on:		Final Re National National State Rec	Landmark Register				
4	Photography: Date of Slides: 11/7 Views: Front Side Re			Date of Photographs fiews: Front □ Side		Other □			
DOCUMENTATION	Research Sources: Abstract of Title Plat Records Plat Map Tax Card & Photo Building Permit Sewer Permit Sanborn Maps	 □ City Directories □ Biographical Encycle □ Obituary Index □ County & City Histori □ Personal Interviews □ Newspapers □ Utah State Historical 	es	□ LDS 0 □ U of U □ BYU 1 □ USU 1 □ SLC L	_ibrary _Ibrary _ibrary		Σ		

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):

Summit County Recorder and Assessor Records, Summit County Courthouse, Coalville, Utah. Sanborn Map, Park City, Utah, 1907.

-
ш
Œ
₽
\vdash
Ж
E
王
O
8
•

Architect/Builder: originally a residential unknown

Building Type/Style: Building Materials: wood bungalow.

Description of physical appearance & significant architectural features:

(Include additions, alterations, ancillary structures, and landscaping if applicable)

Presently, a one-story frame with a gable roof, and alumunum siding. Tax photos indicate a "major" alteration, since the structure originally appeared as a frame bungalow with hip roof.

	6
•	

Statement of Historical Significance:

- ☐ Aboriginal Americans
- □ Agriculture
- □ Architecture
- □ The Arts
- □ Commerce
- □ Communication
- □ Conservation
- □ Education
- ☐ Exploration/Settlement
- □ Industry

- □ Military
- □ Mining
- □ Minority Groups
- ☐ Political
- □ Recreation

- ☐ Religion
- □ Science
- ☐ Socio-Humanitarian
- □ Transportation

Names associated with the structure:

- 1. Thomas M. Stringer.
- 2. Issac L. Osborne.
- 3. 1919- mortgaged from Alice E. Deighton to Samuel B. Dunn.
- 4. 1924, Herman Hethke.

Researcher: Date: Philip F. Notarianni

August, 1978

Utah State Historical Society Historic Preservation Research Office

Structure/Site Information Form

IDENTIFICATION _	Street Address:	569 Park	Ave.				Plat	ocsBI.	5 Lot	17-18
ATI	Name of Structu	ire:					T.	R.	S.	
TIFIC	Present Owner:	: Dona1d R	. Neil, et.a	1.			UTM	1:		
DEN	Owner Address)		Tax	#:	PC-82	
2	Original Owner:			Construc	tion Da	te: @1923	Demol	ition	Date:	
	Original Use:	resident	ia1							
AGE/CONDITION/USE	Present Use: Single-Family Multi-Family Public Commercial		□ Park □ Industrial □ Agricultural	□ Vacar □ Religi □ Other	ous		Occi	upan	ts:	
AGE/0	Building Condi Excellent Good Deteriorated	tion:	□ Site □ Ruins	Integrity: □ Unaltered □ Minor Alte & Major Alte	erations	completely	y changed			44
3 STATUS	Preliminary Eva Significant Contributory Not Contributory Intrusion	aluation: (see desc	ription)		□ Nat □ Nat	I Register S ional Landmark ional Register te Register		ource		
4	Photography: Date of Slides: Views: Front S	11/77 ide □ Rear □	Other □		e of Photog ws: Front 🗅	ıraphs: 1 Side □ Rear [□ Other □			
DOCUMENTATION	Research Source Abstract of Title Plat Records Plat Map Tax Card & Photo Building Permit Sewer Permit Sanborn Maps	es:	☐ City Directories☐ Biographical Er☐ Obituary Index☐ County & City F☐ Personal Interv☐ Newspapers☐ Utah State History	ncyclopedias Histories		LDS Church Arc LDS Genealogic U of U Library BYU Library USU Library SLC Library Other				-

Bibliographical References (books, articles, records, interviews, old photographs and maps, etc.):

Summit County Recorder and Assessor Records, Summit County Courthouse, Coalville, Utah. Sanborn Map, Park City, Utah 1907.

5
Æ
ΣĪ
TEC
H
A.

Architect/Builder: unknown

Building Materials: wood

Building Type/Style:

originally a residential

Description of physical appearance & significant architectural features: (Include additions, alterations, ancillary structures, and landscaping if applicable)

bungalow.

Presently, a one story frame with a gable roof, and aluminum siding. Tax photographs indicate a "major" alteration, since the structure originally appeared as a frame bungalow with a hip roof.

1	C	•	
1	•	,	

Statement of Historical Significance:

- ☐ Aboriginal Americans
- □ Agriculture
- □ Architecture
- □ The Arts
- □ Commerce

- □ Communication
- □ Conservation
- □ Education
- ☐ Exploration/Settlement
- □ Industry
- □ Military
- ☐ Mining
- $\ \square \ \ Minority \ Groups$
- □ Political
 □ Recreation
- ☐ Religion
- ☐ Science
- □ Socio-Humanitarian
- ☐ Transportation

Names associated with the structure:

- 1. Thomas M. Stringer.
- 2. Issac L. Osborne.
- 3. 1919-mortgaged from Alice E. Deighton to Samuel B. Dunn.
- 4. 1924, Herman Hethke.