BUS CHARGER INSTALLATION PROPOSAL - EVALUATION WORKSHEET - May 2023													
	Attended Pre- submission Meeting?	Answered Required Questions?	Included Cover Sheet?			Qualifications and		Subcontractors and Suppliers Report	Work Under Contract Report	Contractor Status Report	Bid Security	Bid Price	Total
Maximum					5	5	35	40	5	5	5		
Hidden Peak	Yes	Yes	Yes	Yes	4.58	4.58	29.17	35.00	4.38	4.38	4.58	\$178,950.00	86.6
Evaluator 1		-	-	-	75%	75%	75%	75%	75%	75%	100%		
Evaluator 2					100%	100%	100%	100%	100%	100%	100%		
Evaluator 3					100%	100%	75%	100%	100%	100%	75%		
Evaluator 4					100%	100%	75%	75%	75%	75%	75%		
Evaluator 5					75%	100%	75%	75%	75%	75%	100%		
Evaluator 6					100%	75%	100%	100%	100%	100%	100%		
PLEMCo	Yes	Yes	Yes	Yes	4.17	4.17	26.25	18.33	3.96	3.54	4.38	\$221,935.00	64.79
Evaluator 1		•	•	•	75%	100%	75%	25%	25%	50%	100%		
Evaluator 2					100%	75%	100%	75%	100%	100%	100%		
Evaluator 3					75%	75%	100%	0%	100%	100%	75%		
Evaluator 4					100%	100%	50%	50%	75%	75%	75%		
Evaluator 5]				50%	100%	50%	50%	75%	75%	75%		
Evaluator 6					100%	50%	75%	75%	100%	25%	100%		

Scoring Instructions

100% = Exceeds Expections, Excellent Work Not Seen Frequently

75% = Meets Expectations With Good Quality Work

50% = Meets Expectations With Average Quality Work

25% = Addressed the Relevant Requirement, but did so poorly.

0% = Ignored the Requirement or Did Not Address it Effectively